

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

LC 060978

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Milnesand Unit

8. Well Name and No.

312

9. API Well No.

30-041-10061

10. Field and Pool, or Exploratory Area

Milnesand (San Andres)

11. County or Parish, State

Roosevelt County, New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Gas
☒ Well ☐ Well Other

2. Name of Operator

MAERSK ENERGY Inc.

3. Address and Telephone No.

2424 Wilcrest, Suite 200, Houston, TX 77042-2753, 713/783-0376

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter G: 1980' from the North Line and 1980' from the East Line SW NE Sec. 19
Township 8S, Range 35E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other PERF & ACID
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) * Work Described: Clean out, deepen, log, reperforate & acid stimulate San Andres producing well. Work Commenced: 08/17/93 Work Completed: 08/25/93

- 1) Moved-in rigged-up workover rig.
- 2) Pulled rods, pump and tubing.
- 3) Cleaned well out to 4713' with 3-7/8" bit.
- 4) Drilled out cement and deepened well from 4735' to 4753'.
- 5) Ran TDT Log from 4753' - 3753'.
- 6) Perforate the San Andres with 4 SPF from 4605' - 4647', 4664' - 4692' and 4730' - 4734'.
- 7) Cleaned out perforations with PerfClean Tool.
- 8) Ran in hole and set packer at 4514'.
- 9) Acidize San Andres with 6,000 gallons of 15% NeFe in 3 - 2,000 gallon stages using salt block as a diverter.
- 10) Swab back 175 bbls of fluid.
- 11) Pulled out of hole with packer.
- 12) Ran in hole with tubing, rods and pump.
- 13) Placed well on production.

14. I hereby certify that the foregoing is true and correct

Signed

George Sheffer

Title

George Sheffer
Drilling Manager

Date


September 24, 1993

(This space for Federal or State office use)

Approved by

Title

Conditions of approval, if any:



Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

REC-11

OCT 01 1993

OFFICE
OFFICE