N. M. M. CONS. COMMISSION Planation: 1930 Mathematicae (1930)

Form A	orm Approved.					
Budget	Bureau	No.	42-R	14	24	

...

Form 9–331	Form Approved. Budget Bureau No. 42-R1424					
Dec. 1973 UNITED STATES	5. LEASE					
DEPARTMENT OF THE INTERIOR	NM-0 P1 5685					
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME					
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME					
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME					
1. oil 🖓 gas 🗔	Horton Federal					
1. oil X gas well Well Other	9. WELL NO.					
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME					
Amoco Production Company 3. ADDRESS OF OPERATOR	Milnesand					
P. O. Box 68, Hobbs, New Mexico 88240	11. SEC., T., R., M., OR BLK. AND SURVEY OR					
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17						
helow)						
AT SURFACE: 330' FNL X 1650 FWL, Unit C AT TOP PROD. INTERVAL: Sec. 30, T-8-S, R-35-E	12. COUNTY OR PARISH 13. STATE					
AT TOTAL DEPTH:	Roosevelt NM					
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,						
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)					
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	4229' RDB					
TEST WATER SHUT OFF						
FRACTURE TREAT						
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion or zone					
PULL OR ALTER CASING	9 1983 change on Form 9-330.)					
MULTIPLE COMPLETE						
	1997年1月1日 1997年 - 秋安 秋日日 日					
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly st including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertin Propose to clean out fill and acidize as fo	 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Propose to clean out fill and acidize as follows: 					
Release nacker null rods and tubing. Run w	orkstring with 3-778" bit and					
clean out fill to 4737'. Sample and analyz	e. Pull workstring and bit. Kun					
in hole with 2-7/8" workstring as follows:	run treating packer, run 2-7/8"					
tubing to supface and set packer at approx	Run 1 joint of 2-7/8" tubing below packer, run treating packer, run 2-7/8" tubing to surface and set packer at approx. 4525'. Run a before treatment					
α_{1} α_{2} α_{2} α_{2} α_{3} α_{2} α_{3} α_{3	a acto with ratio attive material					
and acidize down 2-7/8" tubing with 7500 ga	and acidize down 2-7/8" tubing with /500 gals of 15% LSI NE HUL dolla concarring					
1 an1/1000 connection inhibitor 10 not exc	1 an1/1000 composion inhibitor . No not exceed 2-3 BFM OF 100 FSI Surface					
$r_{\rm rescalar} = S_{\rm rescalar} + r_{\rm rescalar} + S_{\rm rescalar} + r_{\rm rescalar} + S_{\rm rescalar} + S_{\rm$	KISI NE HUL ACIA ANA PUMP PIDUK CON-					
sisting of 300# graded rock salt and 100# m brine, repeat, and flush with 30 bbl of fre	sch water Rum after treatment gamma					
ray temp survey from 4730'-4550'. Release	packer, pull tubing, rods and tailpi					
0+4-BLM R 1-HOU J-F. J. Nash, HOU 1-S Subsurface Safety Valve: Manu. and Type	SUSP 1-PJS Set @ Ft.					
18. I hereby certify that the foregoing is true and correct SIGNED UTTUR AST. Adm. A	Analyst4-15-83					
	SIGNED V VVVV IIILE DATE DATE					
(Original) DESTER W CHESTER						
	DATE					
CONDITIONS OF APPROVAL, IF ANY:						
APR 2 5 1983						

Run in hole with 2-7/8" bing with seating nipple on bo m. Land sand at 4676'. Return to production.

and a second second

1

APR 2 6 1983

O.C.D. HOBBS OFFICE