

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N. M. DISTRICT, BUREAU OF LAND MANAGEMENT
P. O. BOX 1960
HOBBS, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

LC 060978

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Milnesand Unit

8. Well Name and No.

27

1. Type of Well

Oil ☐ Well Gas ☐ Well
☒ Well ☐ Other

2. Name of Operator

MAERSK ENERGY Inc.

9. API Well No.

30-041-10150

3. Address and Telephone No.

2424 Wilcrest, Suite 200, Houston, TX 77042-2753, 713/783-0376

10. Field and Pool, or Exploratory Area

Milnesand (San Andres)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter I: 1720' from the South Line and 660' from the East Line NE SE Sec. 19
Township 8S, Range 35E

11. County or Parish, State

Roosevelt County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other PERF & ACID
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work Described: Clean-out well to PBTD. Reperforate and acid stimulate the San Andres.

Work Commenced: 09/29/93 Work Completed: 10/14/93

Operations Detail:

- 1) Move-in rig-up workover rig.
- 2) RIH with 3-7/8" bit. Clean out well to PBTD of 4746'.
- 3) Perforated San Andres with 4 SPF 4656' - 4698', and 4704' - 4740'.
- 4) Wash and clean perforation with PerfClean Tool.
- 5) Set packer at 4604'.
- 6) Acidize San Andres with 4500 gallons of 15% NeFe Acid in 3 - 1500 gallon stages using rock salt as a diverter between stages.
- 7) Swab back 400 BBLS of fluid.
- 8) POOH with packer.
- 9) Run tubing, pump, and rods.
- 10) Install pumping unit.
- 11) RDMO workover rig.
- 12) Place well on production.

14. I hereby certify that the foregoing is true and correct

Signed

George Sheffer

Title

George Sheffer
Drilling Manager

Date

October 20, 1993

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: