

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
2. Name of Operator <b>Sunray DX Oil Company</b>		5. State Oil & Gas Lease No. <b>K-3935</b>	
3. Address of Operator <b>Box 2880 Dallas, Texas</b>		7. Unit Agreement Name	
4. Location of Well UNIT LETTER <b>C</b> , <b>1880</b> FEET FROM THE <b>West</b> LINE AND <b>660</b> FEET FROM THE <b>North</b> LINE, SECTION <b>34</b> TOWNSHIP <b>7-8</b> RANGE <b>33-E</b> NMPM.		8. Farm or Lease Name <b>New Mexico "AZ" State</b>	
15. Elevation (Show whether DF, RT, GR, etc.) <b>4410 D.F.</b>		9. Well No. <b>11-Y</b>	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data		10. Field and Pool, or Wildcat <b>Chaveroo San Andres</b>	
NOTICE OF INTENTION TO:		12. County <b>Roosevelt</b>	

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MI & RU workover rig.
2. Pulled rods & tubing.
3. Ran Select Rubber Liner. Set @ 4188 to 4224 over perfs (4195 - 4214).
4. Fraced down casing (perfs 4240 - 4340) w/30,000 gal lease crude and 40,000# sand. Mixed Adomite in crude 1#/40 gal.
5. After 1st 10,000 gal dropped 6 RBS. 300# increase. Dropped 4 RBS. 500# increase. Finished frac. Average treating pressure 2400#. AIR 31.2 BPM.
6. Fished rubber liner.
7. Re-ran rods & tubing. Put well on pump.
8. Now recovering load.
9. Will test when all load recovered.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Hastings John Hastings TITLE District Engineer DATE 4-25-68

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: