

Form 9-331  
May 1963)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

MINERAL COMMISSION  
SUBMITTAL INSTRUCTIONS  
P.O. BOX 1100  
WASHINGTON, D.C. 20540  
Instructions on reverse side

Form approved,  
BUDGET BUREAU No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)		5. LEASE DESIGNATION AND SERIAL NO. NM-0556301
6. IF INDIAN, ALLOTTEE OR TRIBE NAME -		7. UNIT AGREEMENT NAME -
8. FARM OR LEASE NAME Federal "C"		9. WELL NO. 1
10. FIELD AND POOL, OR WILDCAT Undesignated		11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA Sec. 30-8S-36E
4. PERMIT NO. -	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4140.5' KB	12. COUNTY OR PARISH Roosevelt
		13. STATE NM

6. Check Appropriate Box To Indicate Nature of Notice, Report, Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF  
FRACTURE TREAT  
SHOOT OR ACIDIZE  
REPAIR WELL  
(Other)

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PULL OR ALTER CASING  
MULTIPLE COMPLETE  
ABANDON\*  
CHANGE PLANS

<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF  
FRACTURE TREATMENT  
SHOOTING OR ACIDIZING  
(Other)

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

REPAIRING WELL  
ALTERING CASING  
ABANDONMENT\*

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugging Procedure as per conversation w/Pete Chester 12-2-82.

1) Set CIBP @ 9700', dump 35' cmt on top of plug.

2) Circulate hole with 9#/gal mud.

3) Spot 25sx plug, 8800'-8700', top of Wolfcamp 8810'.

4) Cut csg off @ 6000', spot 35sx plug half-in & half-out of csg stub, 5950'-6050', TOC @ 8200'.

5) Spot 45sx plug, half-in & half-out of 8 5/8" csg shoe @ 4082', 4030'-4130'.

6) Cut off 8 5/8" csg at 1000', spot 50sx plug half-in & half-out of 8 5/8" csg stub, 950'-1050'.

7) Spot 40sx plug across 13 3/8" csg shoe @ 370', 320'-420'.

8) Set 50' plug (10sx) at surface w/4"X10' dry hole marker w/well description.

9) Clean location & prepare for inspection.

I hereby certify that the foregoing is true and correct.

SIGNED

*James A. Gillham*

TITLE, Drilling & Production Manager

DATE 12-2-82

(This space for Federal or State office use)

DEC 8 1982

APPROVED BY

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

DATE

CONDITIONS OF APPROVAL IF ANY.