

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 4039

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR The Maurice L. Brown Company	8. FARM OR LEASE NAME Option 694 Ltd.
3. ADDRESS OF OPERATOR Suite 200, Sutton Place Bldg., Wichita, Kansas 67202	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter "I" 1980' from South Line & 510' from East Line, Sec.35,T-3-S, R-35-E	10. FIELD AND POOL, OR WILDCAT Vada Penn
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 35-8S-35E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4146' GL; 4157' KB	12. COUNTY OR PARISH Roosevelt
	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACTURE TREAT	MULTIPLE COMPLETION
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in and rig up casing pulling rig.
2. Attempt to salvage 5 1/2" casing from point of casing separation at 6525'.
3. If casing cannot be pulled from 6525', set a cement retainer at 6475' and squeeze cement with 100 sx. cement.
4. Salvage 5 1/2" at free point.
5. Enter 5 1/2" stub and spot 35 sx. cement 50' cement below top of stub.
6. Tag top of cement.
7. Spot 35 sx. cement at 4093' to form 100' plug across 8 5/8" csg. shoe at 4043'. Tag top of cement.
8. Spot 70 sx. cement at 2300' to form 200' plug from 2300' to 2100'.
9. Salvage 3 5/8" casing from approx. 1200'.
10. Spot 50 sx. cement thru tubing 50' below 3 5/8" csg. stub.
11. Tag top of cement.
12. Spot 50 sx. cement thru tbg. at 425' to form 100' cement plug across 10 3/4" casing shoe at 375'. Tag top of cement.
13. Place 10 sx. cement at surface.
14. Erect dry hole marker.
15. Clean and level location.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

District Engineer

DATE

1-10-78

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED
AS AMENDED
JAN 13 1978

*See Instructions on Reverse Side

W. R. BROWN
DISTRICT ENGINEER