ENERGY AND MINERALS DEPARTMENT	
	Form C-103
DISTRIBUTION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501	Revised 10-1-78
TILE CONTRACTOR	Sa. Indicate Type of Leuse
U.S.O.S.	State X For
LAND OFFICE	5. State Cli & Gas Lease No.
OPERATOR	K-1371-1 & L-737
SUNDRY NOTICES AND REPORTS ON WELLS	
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FOR PROPOSALS TO EPILL OR TO GEEPIN OR PLUG BACK TO A DIFFERENT RESERVOIR. 100 NOT USE THIS FOLLICATION FOR PERMIT - "FORM CHICIT FOR SUCH PROPOSALS."	
۱	7, Unit Agreement Name
OIL GAB OTHER-	8. Farm or Lease Hame
2. Name al Operator	Blond State Comm.
The Maurice L. Brown Company	9, Well No.
3. Address of Operator	1
Suite 200/Sutton Place Bldg. Wichita, Kansas 67202	10. Field and Pool, or Wildcat
4. Location of Well	Vada Penn
UNIT LETTER M 660 FEET FROM THE SOUTH LINE AND 660 FEET FROM	
THE West LINE, SECTION 32 TOWNSHIP 85 RANGE 35E NMPM.	
THE West LINE, SECTION 32 TOWNSHIP 85 RANGE 35E NMPM.	
ALL IS. Elevation (Show whether DF, RT, GR, etc.)	12. County
4212.6 <u>GR</u>	Roosevelt
16. Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ner Data
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
	ALTERING CASING
PERFORM HEMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	PLUE AND ABANDONMENT
TEMPORARILY ABANDON	
PULL OR ALTER CABING	
	estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1903.	
10-15-84Moved in and rigged up PBCP Services, Inc. Pulled out o	f hole with 234
joints of 2 3/8" tubing. Picked up HOWCO cement retaine	r and ran in hole
on 234 joints of tubing. Set retainer at 7262' KB depth	. Mixed and pumped
100 sacks cement. Displaced cement with 30 barrels of f	resh water. Pulled
out of retainer. Pumped 150 barrels of salt gel mud. L	acked approximately
50 barrels loading hole.	
10-16-84Completed loading hole with 50 barrels of salt gel mud.	Picked up on 5 1/2"
	1/2" anaing collar
casing and removed slips. Ran string shot and shot in 5	1/2" casing collar
at 4501' depth. Casing not free. Pumped into casing an	1/2" casing collar d pressured to 1500#.
at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit	<pre>1/2" casing collar d pressured to 1500#. h no progress.</pre>
at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta	<pre>1/2" casing collar d pressured to 1500#. h no progress.</pre>
at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between</pre>
at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135</pre>
at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing.</pre>
at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing.</pre>
at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface.	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could</pre>
at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface. 10-18-84No change in casing overnight. Made 2nd shot in 5 1/2"	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could casing collar at</pre>
 at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface. 10-18-84No change in casing 30 minutes. Not free. Made 3rd sh 	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could casing collar at</pre>
<pre>at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface. 10-18-84No change in casing overnight. Made 2nd shot in 5 1/2"</pre>	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could casing collar at</pre>
 at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface. 10-18-84No change in casing overnight. Made 2nd shot in 5 1/2" 4302'. Worked casing 30 minutes. Not free. Made 3rd sh 16. Thereby certify that the information above is true and complete to the best of mr knowledge and belief. 	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could casing collar at</pre>
 at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface. 10-18-84No change in casing 30 minutes. Not free. Made 3rd sh 	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could casing collar at</pre>
 at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface. 10-18-84No change in casing overnight. Made 2nd shot in 5 1/2" 4302'. Worked casing 30 minutes. Not free. Made 3rd sh 18. Pereby certify the information above is true and complete to the best of my knowledge and belief. 	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could casing collar at ot in 5 1/2" casing</pre>
 at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface. 10-18-84No change in casing overnight. Made 2nd shot in 5 1/2" 4302'. Worked casing 30 minutes. Not free. Made 3rd sh 18. Pereby certify the information above is true and complete to the best of my knowledge and belief. 	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could casing collar at ot in 5 1/2" casing</pre>
 at 4501' depth. Casing not free. Pumped into casing an Would not take fluid. Worked casing for 1 1/2 hours wit Started picking up 1" tubing with mule shoed bottom. Ta 10 joints. 10-17-84Rigged up Fannie Lee Mitchell kill truck and started was 8 5/8" casing and 5 1/2" casing. Washed to approximatel joints. Quit making progress. Laid down 1" tubing. Pi Casing not free. Pumped into casing. Could pump in at not establish circulation to surface. 10-18-84No change in casing overnight. Made 2nd shot in 5 1/2" 4302'. Worked casing 30 minutes. Not free. Made 3rd sh 16. Thereby certify that the information spore is true and complete to the best of mr knowledge and belief. 	<pre>1/2" casing collar d pressured to 1500#. h no progress. gged up at 310' with hing down between y 4185' with 135 cked up on casing. 1500# but could casing collar at ot in 5 1/2" casing</pre>

Blond No. 1 (cont.)

10-18-84 (cont.)

collar at 4131'. Casing was free at this point. Laid down 127 joints 5 1/2" casing plus 5' top piece. Total tally 4158.60'. Ran tubing to 4501' and spotted 10 sacks cement at first shot point. Raised tubing to 4302' and spotted 10 sacks cement. Raised tubing to 4181' and spotted 50 sacks cement across 5 1/2" casing stub.

10-19-84

Tagged top of cement at 4095'. Spotted 65 sacks cement through tubing "at 4095'. Spotted 35 sacks cement through tubing at 2100' across top of salt section. Pulled out of hole with tubing. Shot 8 5/8" casing in collar at 811'. Could not circulate. Worked casing 45 minutes. Pressured to 1000 psi and left in slips with 100,000# strain.

10-22-84

No change in 8 5/8" casing over weekend. Worked casing for 1 1/2 hours with no progress. Shot 8 5/8" casing collar at 604'. Casing not free. Could circulate a little. Worked casing for 1 hour with no progress. Made shot in 8 5/8" casing collar at 481'. Casing not free. Worked loose in 15 minutes. Laid down 12 joints (480.10') 8 5/8", J-55,ST&C, Range 3 casing. Ran tubing to 840'. Spotted 15 sacks cement across shot point. Raised tubing to 530'. Spotted 130 sacks to provide 100' plug across 8 5/8" stub plus a 100' plug across 12 3/4" casing shoe.

10-23-84

Tagged top of cement at 280'. Completed laying down tubing. Spotted 10 sacks cement in top of 12 3/4" surface casing. Erected dry hole marker. Rigged down PBCP Services, Inc.

÷.,

RECEIVED TOT 26 1984 MOBBES C.....