Form 9-331 (May 1963)	DEPARTM	NIT STATES ENT OF THE INTER OLOGICAL SURVEY	SUBMIT IN TELPLICS OF CORRECT OR CORRECT INSTRUCTIONS OF CORRECT OR CORRECT O	Touris moreowed. Noticed Director New of SOCIAC. 5. LEASE DESIGNATION AND SOCIAC TO
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this term for proposals to drill or to despen or pair back to a different reservoir, Use "APPLICATION FOR PERMIT of for such proposals.)				6. IF INDIAN, ALLOTTEN OR TRUSH NAME
I. oil Cas				7. UNIT AGLEGMENT NAME
WELL WELL OTHER 2. NAME OF OPERATOR PIERCE & DEHLINGER				8. FARM OR TEASE NAME Union Federal
3. ADDRESS OF OPERATOR				9. WELL NO.
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)				10. FIELD AND POOL, OR WILDCAT
At surface				11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO.		15. ELEVATIONS (Show whether D	F, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
16.	Check App		Nature of Notice, Report, or (Other Data
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 7. DESC HEE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinen proposed work. If well is directionally drilled, give subsurface locat nent to this work.)*			t details, and give pertinent dates	s of multiple completion on Well bletion Report and Log form.) s, including estimated date of starting any cal depths for all markers and zones perti-
PAGE 2	5-18-72 W.O.O.			op of cmt. @ 7540'; ' above float collar.
	5-21-72	Ran tbg. & bit; drld. out rubber plug and drld. cmt.; left 5 ft. of cmt. in pipe; plug back 9620'; T.D. 9625' Perforated 1 shot/ foot from 9594½-9615½' (22 holes)		
	5-23-72 Ran Model R pkr. on tbg. & set pipe to 9611'; removed BOP; in w/ 1000 gals. 15% MCA; break detreated @ 5-3/4 BPM @ 1700#; Ibbls. acid and 38 bbls. flush			talled tbg. head; acidiz wn pressure 3100#; IP = 0; total load 24
		surface: swbd	to pits 55 bbls. 1	5-22-72; FL 6500' fr. load & acis wtr in 5 .; while swbg @ 10 bbls