STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION DISTRIBUTION SANTA FE FILE FILE	Fora C-103 Revised 10-1-73
U.S.G.S. LAND OFFICE	Sa. Indicate Type of Lease State X Fee
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO CHILL OR TO OFFICIA OF PLUG BACK TO A DIFFERENT RESERVOIR. 1. 014 CAS CAS COTHER- RE-ENTRY	7. Unit Agreement flame
Yates Petroleum Corporation	8. Fain of Leave tiene Gulf XE State 9. Well No.
207 South 4th St., Artesia, NM 88210	1
4. Location of Well C 660 North 1980 UNIT LETTER FEET FROM THE FEET FROM	10. Field and Lori, or Window Und. NW Todd SA
West 20 7S 35E NMPM.	
15. Eleventen (Show whether DF, RT, GR, etc.) 4261 GR	12. County Roosevelt
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. PULL ON ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JQB OTHER Re-entry, Perform	ALTERING CASING DUG AND ABANDONMENT

27. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starring any proposed work) SEE RULE 1103.

Re-entered well 6-8-83. Drilled cement in 8-5/8" 24% casing. Drilled out surface plug at 130'. Tagged 2nd plug at 1465'. Drilled 3rd plug ag 4103'. Drilled to 4316'. Tested casing to 2000 psi, okay. COOH w/tubing and bit. Set CIBP at 4300' w/10' of cement on top. WIH and perforated $4247\frac{1}{2}-4274'$ w/15 .70" holes as follows: $4247\frac{1}{2}$, 51, 52, 53, 54, 58, 59, 60, 61, 64, 65, 67, 68, 72, and 74'. RIH w/tubing and packer. Spot acid over perfs at $4247\frac{1}{2}-4274'$. Set packer at 4211'. Acidized perfs w/2500 gallons 20% NEFE acid and 20 ball sealers. Swabbed well. COOH w/tubing. WIH and perforated 4164-4216' w/15 .70" holes as follows: 4164, $64\frac{1}{2}$, $65\frac{1}{2}$, 74, 75, 85, 86, 91, 92, 4212, 13, 14, $15\frac{1}{2}$, and 16'. RIH w/tubing and packer. Spot acid over perfs at collows: 4164, $64\frac{1}{2}$, $65\frac{1}{2}$, 74, 75, 85, 86, 91, 92, 4212, 13, 14, $15\frac{1}{2}$, and 16'. RIH w/tubing and packer. Spot acid over perfs 4212-4216' and treated w/750 gallons 20% HCL acid and 25 ball sealers. Swabbed well dry. POOH w/tools. WIH and perforated 4119-42' w/14 .70" holes as follows: 4119, 20, 21, 22, 23, 24, 25, 33, 34, 35, 36, 39\frac{1}{2}, 40 and 42'. RIH w/tubing and packer. Treat perfs 4119-42' w/3000 gallons 15% NEFE acid and 21 ball sealers. Swabbing well. POOH w/packer and plug. Hung well on pump. Begin pumping back load.

AMENDED REPORT

ismes in the day to del	W Production Superviso:	r DATE <u>6-29-83</u>
ORIGINAL SIGNED BY EDDIE SE		