Form 9-331 (May 1963)						
	DEPARTME	ED STATES OF THE INTERI	SUBMIT IN TRIPLICAT (Other instructions verse side)	re- 5. LEASE DESIGNATION	au No. 42–R14	
	GEOLO	GICAL SURVEY	·	NM-0338A		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)				-	6. IF INDIAN, ALLOTTEE OR TRIBE NAM	
1.		-	· · · · · · · · · · · · · · · · · · ·	7. UNIT AGREEMENT NA	ME	
OIL & GAS WELL WELL OTHER 2. NAME OF OPERATOR TEXACO Inc.					Little Lucky Lake Unit 8. FARM OR LEASE NAME Peery Federal	
3. ADDRESS OF OPERAT		vice 99240		9. WELL NO.		
4 LOCATION OF WELL	- Hobbs, New Me	d in accordance with any	State requirements.*	10. FIELD AND POOL, O	R WILDCAT	
See also space 17 below.) Well located 1980' from the North line and 1980' from the East line of Section 29, T-15-S, R-30-E,					Little Lucky Lake Devo	
Unit Letter '		ection 29, 1-10	5-5, K-30-E,	11. SEC., T., B., M., OB I SURVEY OR AREA	BLK. AND	
	-			Sec. 29, T-15	-S, R-30	
14. FERMIT NO.	15. ELE	EVATIONS (Show whether DF	, RT, GR, etc.)	12. COUNTY OB PARISH	13. STATE	
REGULAR		3968' DF	······································	Chaves	New Mex	
16.	Check Appropria	te Box To Indicate N	lature of Notice, Report, or	r Other Data		
	NOTICE OF INTENTION TO :			EQUENT REPORT OF:		
TEST WATER SHUT	-OFF PULL OR A	ALTER CASING	WATER SHUT-OFF	REPAIRING	WELL	
FRACTURE TREAT	MULTIPLE	COMPLETE	FRACTURE TREATMENT	ALTERING C.	ASING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONME	NT*	
REPAIR WELL	CHANGE P	LANS	(Other)			
(Other)			Completion or Record	ilts of multiple completion mpletion Report and Log for	rm.)	
3. Squeeze pe 4. Pulled tub	retainer and se rforations 11,05 ing.	60'-11,134' w/30	00 sx Class 'C' ceme	ent w/.6% Halad S	9.	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran product</li> </ol>	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa	50'-11,134' w/30 71 JSPF from 11, 5et packer at 10 90 gals. 15% NEA vater. Pulled t 15 and return to	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack p production.	r after each 100 ker.	gals.	
2. Run cement 3. Squeeze pe 4. Pulled tub 5. Perforate 6. Ran tubing 7. Acidize pe 8. Kill well 9. Ran produc 10. On 24 hour	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa	50'-11,134' w/30 Set packer at 10 Ogals. 15% NEA Water. Pulled to b and return to A.M., March 22	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack p production. 2, 1971. Flowed 120	r after each 100 ker. 6 bbls oil and 64	gals. 42	
2. Run cement 3. Squeeze pe 4. Pulled tub 5. Perforate 6. Ran tubing 7. Acidize pe 8. Kill well 9. Ran produc 10. On 24 hour	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30	50'-11,134' w/30 Set packer at 10 Ogals. 15% NEA Water. Pulled to b and return to A.M., March 22	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack p production. 2, 1971. Flowed 120	r after each 100 ker. 6 bbls oil and 64 <b>RE</b>	gals. 42	
2. Run cement 3. Squeeze pe 4. Pulled tub 5. Perforate 6. Ran tubing 7. Acidize pe 8. Kill well 9. Ran produc 10. On 24 hour	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30	50'-11,134' w/30 Set packer at 10 Ogals. 15% NEA Water. Pulled to b and return to A.M., March 22	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack p production. 2, 1971. Flowed 120	r after each 100 ker. 6 bbls oil and 64 REC Mac	gals. 42 CEIVI	
2. Run cement 3. Squeeze pe 4. Pulled tub 5. Perforate 6. Ran tubing 7. Acidize pe 8. Kill well 9. Ran produc 10. On 24 hour	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30	50'-11,134' w/30 Set packer at 10 Ogals. 15% NEA Water. Pulled to b and return to A.M., March 22	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack p production. 2, 1971. Flowed 120	r after each 100 ker. 6 bbls oil and 64 REC Mac	gals. 42 CEIVI	
2. Run cement 3. Squeeze pe 4. Pulled tub 5. Perforate 6. Ran tubing 7. Acidize pe 8. Kill well 9. Ran produc 10. On 24 hour	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30	50'-11,134' w/30 Set packer at 10 Ogals. 15% NEA Water. Pulled to b and return to A.M., March 22	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack p production. 2, 1971. Flowed 120	r after each 100 ker. 6 bbls oil and 64 REG MAA	gals. 42 CEIV 825 1971	
2. Run cement 3. Squeeze pe 4. Pulled tub 5. Perforate 6. Ran tubing 7. Acidize pe 8. Kill well 9. Ran produc 10. On 24 hour	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30	50'-11,134' w/30 Set packer at 10 Ogals. 15% NEA Water. Pulled to b and return to A.M., March 22	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack p production. 2, 1971. Flowed 120	r after each 100 ker. 6 bbls oil and 64 REG MAA	gals. 42 <b>CEIVI</b> 825 1971	
2. Run cement 3. Squeeze pe 4. Pulled tub 5. Perforate 6. Ran tubing 7. Acidize pe 8. Kill well 9. Ran produc 10. On 24 hour	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30	50'-11,134' w/30 Set packer at 10 Ogals. 15% NEA Water. Pulled to b and return to A.M., March 22	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack p production. 2, 1971. Flowed 120	r after each 100 ker. 6 bbls oil and 64 REG MAA	gals. 42 CEIV 25 1971	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour</li> <li>bbls water</li> </ol>	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30	O'-11,134' w/30 I JSPF from 11, Ogals. 15% NEA Water. Pulled t ab and return to A.M., March 22 OR 1720, 30/64	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack production. 2, 1971. Flowed 126 ' choke.	r after each 100 ker. 6 bbls oil and 64 REC Mac	gals. 42 <b>CEIVI</b> 825 1971	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour</li> <li>bbls water</li> </ol>	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30 . Grav. 56.2, G	GO'-11,134' w/30 (1 JSPF from 11, Get packer at 10 O gals. 15% NEA vater. Pulled to the and return to O A.M., March 22 GOR 1720, 30/64' d correct Ass	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack o production. 2, 1971. Flowed 120 ' choke.	r after each 100 ker. 6 bbls oil and 64 <b>REG</b> <i>MAR</i> <i>U. S. GEOL</i> <i>ARTESIA</i> ,	gals. 42 CEIV R25 1971 Ogical Su NEW MEX	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour bbls water</li> </ol> 18. I hereby certify the SIGNED	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30 . Grav. 56.2, G	GO'-11,134' w/30 (1 JSPF from 11, Get packer at 10 O gals. 15% NEA vater. Pulled to the and return to O A.M., March 22 GOR 1720, 30/64' d correct Ass	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack production. 2, 1971. Flowed 126 ' choke.	r after each 100 ker. 6 bbls oil and 64 REG MAA	gals. 42 CEIVE 25 1971 Ogical Su NEW MEX	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour</li> <li>bbls water</li> </ol> 18. I hereby certify that SIGNED	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30 . Grav. 56.2, G	GO'-11,134' w/30 (1 JSPF from 11, Get packer at 10 O gals. 15% NEA vater. Pulled t and return to A.M., March 22 GOR 1720, 30/64' d correct Ass 	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack o production. 2, 1971. Flowed 120 ' choke.	r after each 100 ker. 6 bbls oil and 64 <b>REC</b> <i>MAR</i> <i>U. 3. GEOL</i> <i>ARTESIA</i> , DATE <u>March</u>	gals. 42 CEIVE 25 1971 Ogical Su NEW MEX	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour</li> <li>bbls water</li> </ol> 18. I hereby certify the SIGNED	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30 . Grav. 56.2, G with formation state office use) Meral or State office use)	GO'-11,134' w/30 (1 JSPF from 11, Get packer at 10 O gals. 15% NEA vater. Pulled to the and return to O A.M., March 22 GOR 1720, 30/64' d correct Ass	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack o production. 2, 1971. Flowed 120 ' choke.	r after each 100 ker. 6 bbls oil and 64 <b>REG</b> <i>MAR</i> <i>U. S. GEOL</i> <i>ARTESIA</i> ,	gals. 42 CEIVE 25 1971 Ogical Su NEW MEXI	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour</li> <li>bbls water</li> </ol> 18. I hereby certify the SIGNED	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30 . Grav. 56.2, G the foregoing is true and deral or State office use) APPROVAL, IF ANY: DOSES	GO'-11,134' w/30 (1 JSPF from 11, Get packer at 10 O gals. 15% NEA vater. Pulled t and return to A.M., March 22 GOR 1720, 30/64' d correct Ass 	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack o production. 2, 1971. Flowed 120 ' choke.	r after each 100 ker. 6 bbls oil and 64 <b>REC</b> <i>MAR</i> <i>U. 3. GEOL</i> <i>ARTESIA</i> , DATE <u>March</u>	gals. 42 CEIVE 25 1971 Ogical Su NEW MEXI	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour</li> <li>bbls water</li> </ol> 18. I hereby certify the SIGNED	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30 . Grav. 56.2, G the foregoing is true and deral or State office use) APPROVAL, IF ANY: PURPOSES	GO'-11,134' w/30 (1 JSPF from 11, Get packer at 10 O gals. 15% NEA vater. Pulled t and return to O A.M., March 22 GOR 1720, 30/64' d correct Ass 	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack production. 2, 1971. Flowed 126 ' choke.	r after each 100 ker. 6 bbls oil and 64 <b>REC</b> <i>MAR</i> <i>U. 3. GEOL</i> <i>ARTESIA</i> , DATE <u>March</u>	gals. 42 CEIVE 25 1971 Ogicial Sur NEW MEXIN	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour</li> <li>bbls water</li> </ol> 18. I hereby certify the SIGNED	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30 . Grav. 56.2, G the foregoing is true and deral or State office use) APPROVAL, IF ANY: PURPOSES	GO'-11,134' w/30 (1 JSPF from 11, Get packer at 10 O gals. 15% NEA vater. Pulled t and return to O A.M., March 22 GOR 1720, 30/64' d correct Ass 	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack o production. 2, 1971. Flowed 120 ' choke.	r after each 100 ker. 6 bbls oil and 64 <b>REC</b> <i>MAR</i> <i>U. 3. GEOL</i> <i>ARTESIA</i> , DATE <u>March</u>	gals. 42 CEIVE 25 1971 Ogicial Sur NEW MEXIN	
<ol> <li>Run cement</li> <li>Squeeze pe</li> <li>Pulled tub</li> <li>Perforate</li> <li>Ran tubing</li> <li>Acidize pe</li> <li>Kill well</li> <li>Ran produc</li> <li>On 24 hour</li> <li>bbls water</li> </ol> 18. I hereby certify the SIGNED	retainer and se rforations 11,05 ing. 5-1/2" casing w/ w/RTTS tool. S rforations w/200 with formation w tion tubing, swa PT ending 10:30 . Grav. 56.2, G with formation state office use) Meral or State office use)	GO'-11,134' w/30 (1 JSPF from 11, Get packer at 10 O gals. 15% NEA vater. Pulled t and return to O A.M., March 22 GOR 1720, 30/64' d correct Ass 	,008'-11,028'. ),967'. A with 1 ball sealer tubing and RTTS pack production. 2, 1971. Flowed 126 ' choke.	r after each 100 ker. 6 bbls oil and 64 <b>REC</b> <i>MAR</i> <i>U. 3. GEOL</i> <i>ARTESIA</i> , DATE <u>March</u>	gals. 42 CEIVE 25 1971 Ogicial Sur NEW MEXIN	

•

-

•

1

ŧ

ME 1971

OL CLARTER CONTRACTOR

## RECEIVED

941.

-

: es

1

MAR 2 6 1971

D. C. C. ARTESIA. OFFICE