rm 3160-5 une 1990)	UNITED STATES DEPARTMENT OF THE INTE	ISIS N. LU. M. D RIOR MORE MORE CELLU	Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUREAU OF LAND MANAGE	MENI	5. Lease Designation and Serial No. NM-25363
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals			6. If Indian, Allottee or Tribe Name
	SUBMIT IN TRIPLICAT		7. If Unit or CA, Agreement Designation
1. Type of Well Oil Gas			8. Well Name and No.
Oil Gas Well Other			Champeau Fed No. 1
2. Name of Operator Nadel and Gussman Permian LLC OGRID # 155615			9, API Well No.
Nadel and Gussman Permian, L.L.C. OGRID # 155615 3. Address and Telephone No. OGRID # 155615			30-005-00518
601 N. Marienfeld, Suite 508, Midland, TX 79701			10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Little Lucky Lake Morrow 11. County or Parish, State
660' FNL & 1980' F\	WL		11. County of Parish, State
Unit C, Sec. 31-15S	-30E		Chaves Co., NM
12. CHECK A	APPROPRIATE BOX(s) TO INDICATE	NATURE OF NOTICE, REPORT,	OR OTHER DATA
TYPE OF	SUBMISSION	TYPE OF ACTION	
	f Intent	Abandonment	Change of Plans
		Recompletion	New Construction
Subsequ	Jent Report	Plugging Back Casing Repair	Non-Routine Fracturing
Einal Ab	andonment Notice	Altering Casing	
		Other	Dispose Water
			(Mote: Report results of multiple completion on Well
13. Describe Proposed or C	Completed Operations (Clearly state all pertinet details,	and give pertinent dates, including estimated dat	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is s work)*
directionally drilled, give 1. Notify Carlsbad B 2. MIRU. Sting out of 3. Pump 40 Bbls 9 F Strawn perfs from 4. Cut off 4" bradeni above old cemen 5. GIH with tubing a Spot a 30 sx "H" Spot a 30 sx "C" Spot a 25 sx "C" 6. Run a CBL strip a casing shoe. Mo 7. Shoot two squee annulus and circo 8. Cut off remainde	E subsurface locations and measured and true ventical LM office 24 hours prior to starting. of the retainer at 9882'. PPG salt gel mud on bottom. Spot 25 sx "H' 1 9400' - 9000'. POH with tubing. head and weld lift nipple on top joint. Set ca at plug at approximately 8350'. POOH with 4 nd fill remainder of hole with 9 PPG salt gel plug across the 4" stub from 8350' - 8250'. plug from 6400' - 6300'. Move up. plug across the 5½" casing shoe from 4550 across intermediate casing shoe at 2929' to	cement on retainer from 9882' - 9500' sing jacks and check the casing free po " liner and lay down. mud. Move up. o' - 4350'. confirm the TOC. Spot a 25 sx plug ac nto annulus and establish circulation. P valves and pump another 25 sx "C" cel	e of starting any proposed work. If well is s work.)" Spot 25 sx "H" cement above bint. By wireline, cut 4" liner ross the 8-5/8" intermediate rump 80 sx "C" cement into the ment in the casing from 550' - 450'
directionally drilled, give 1. Notify Carlsbad B 2. MIRU. Sting out of 3. Pump 40 Bbls 9 F Strawn perfs from 4. Cut off 4" braden above old cemen 5. GIH with tubing a Spot a 30 sx "H" Spot a 30 sx "C" 6. Run a CBL strip a casing shoe. Mo 7. Shoot two squee annulus and circ 8. Cut off remainder 9. Clean location an	a subsurface locations and measured and true ventical LM office 24 hours prior to starting. of the retainer at 9882'. PPG salt gel mud on bottom. Spot 25 sx "H' in 9400' - 9000'. POH with tubing. head and weld lift nipple on top joint. Set can at plug at approximately 8350'. POOH with 4 nd fill remainder of hole with 9 PPG salt gel plug across the 4" stub from 8350' - 8250'. plug from 6400' - 6300'. Move up. plug across the 5½" casing shoe from 4550 across intermediate casing shoe at 2929' to ve up. ze perfs in the 8-5/8" casing at 543'. Pump ulate to the surface. Close the bradenhead r of wellhead and spot a 10 sx "C" plug at the ind haul off any remaining equipment.	cement on retainer from 9882' - 9500' sing jacks and check the casing free po " liner and lay down. mud. Move up. o' - 4350'. confirm the TOC. Spot a 25 sx plug ac nto annulus and establish circulation. P valves and pump another 25 sx "C" cel	e of starting any proposed work. If well is s work.)" Spot 25 sx "H" cement above bint. By wireline, cut 4" liner ross the 8-5/8" intermediate rump 80 sx "C" cement into the ment in the casing from 550' - 450'
directionally drilled, give 1. Notify Carlsbad B 2. MIRU. Sting out of 3. Pump 40 Bbls 9 F Strawn perfs from 4. Cut off 4" braden above old cemen 5. GIH with tubing a · Spot a 30 sx "C" · Spot a 30 sx "C" · Spot a 25 sx "C" 6. Run a CBL strip a casing shoe. Mo 7. Shoot two squee annulus and circ 8. Cut off remainder 9. Clean location an 14. I hereby certify that the Signed	a subsurface locations and measured and true ventical LM office 24 hours prior to starting. of the retainer at 9882'. PPG salt gel mud on bottom. Spot 25 sx "H' in 9400' - 9000'. POH with tubing. head and weld lift nipple on top joint. Set ca at plug at approximately 8350'. POOH with 4 nd fill remainder of hole with 9 PPG salt gel plug across the 4" stub from 8350' - 8250'. plug from 6400' - 6300'. Move up. plug across the 5½" casing shoe from 4550 across intermediate casing shoe at 2929' to ve up. ze perfs in the 8-5/8" casing at 543'. Pump ulate to the surface. Close the bradenhead r of wellhead and spot a 10 sx "C" plug at the ad haul off any remaining equipment.	cement on retainer from 9882' - 9500' sing jacks and check the casing free po " liner and lay down. mud. Move up. ' - 4350'. confirm the TOC. Spot a 25 sx plug ac nto annulus and establish circulation. P valves and pump another 25 sx "C" cel e surface'. Set a regulation 4" x 4' dry h	e of starting any proposed work. If well is s work.)" Spot 25 sx "H" cement above oint. By wireline, cut 4" liner ross the 8-5/8" intermediate rump 80 sx "C" cement into the ment in the casing from 550' - 450' ole marker.
directionally drilled, give 1. Notify Carlsbad B 2. MIRU. Sting out of 3. Pump 40 Bbls 9 F Strawn perfs from 4. Cut off 4" braden above old cemen 5. GIH with tubing a Spot a 30 sx "H" Spot a 30 sx "C" 6. Run a CBL strip a casing shoe. Mo 7. Shoot two squee annulus and circ 8. Cut off remainder 9. Clean location and 14. I hereby certify that the Signed (CRIG. S	a subsurface locations and measured and true ventical of the retainer at 9882'. PPG salt gel mud on bottom. Spot 25 sx "H' a 9400' - 9000'. POH with tubing. head and weld lift nipple on top joint. Set can at plug at approximately 8350'. POOH with 4 nd fill remainder of hole with 9 PPG salt gel plug across the 4" stub from 8350' - 8250'. plug from 6400' - 6300'. Move up. plug across the 5½" casing shoe from 4550 across intermediate casing shoe at 2929' to ve up. ze perfs in the 8-5/8" casing at 543'. Pump i ulate to the surface. Close the bradenhead r of wellhead and spot a 10 sx "C" plug at the nd haul off any remaining equipment. a foregoing is true and correct Title R	cement on retainer from 9882' - 9500' sing jacks and check the casing free po " liner and lay down. mud. Move up. 1' - 4350'. confirm the TOC. Spot a 25 sx plug ac nto annulus and establish circulation. F valves and pump another 25 sx "C" cel e surface'. Set a regulation 4" x 4' dry h	e of starting any proposed work. If well is s work.)* . Spot 25 sx "H" cement above pint. By wireline, cut 4" liner ross the 8-5/8" intermediate . ump 80 sx "C" cement into the ment in the casing from 550' - 450' ole marker.
directionally drilled, give 1. Notify Carlsbad B 2. MIRU. Sting out of 3. Pump 40 Bbls 9 F Strawn perfs from 4. Cut off 4" braden above old cemen 5. GIH with tubing a Spot a 30 sx "H" Spot a 30 sx "C" Spot a 25 sx "C" 6. Run a CBL strip a casing shoe. Mo 7. Shoot two squee annulus and circ 8. Cut off remainded 9. Clean location and 14. I hereby certify that the Signed (ORIG. S	a subsurface locations and measured and true ventical of the retainer at 9882'. PPG salt gel mud on bottom. Spot 25 sx "H' a 9400' - 9000'. POH with tubing. head and weld lift nipple on top joint. Set can at plug at approximately 8350'. POOH with 4 nd fill remainder of hole with 9 PPG salt gel plug across the 4" stub from 8350' - 8250'. plug from 6400' - 6300'. Move up. plug across the 5½" casing shoe from 4550 across intermediate casing shoe at 2929' to ve up. ze perfs in the 8-5/8" casing at 543'. Pump i ulate to the surface. Close the bradenhead r of wellhead and spot a 10 sx "C" plug at the nd haul off any remaining equipment. a foregoing is true and correct Title R	cement on retainer from 9882' - 9500' sing jacks and check the casing free po " liner and lay down. mud. Move up. ' - 4350'. confirm the TOC. Spot a 25 sx plug ac nto annulus and establish circulation. P valves and pump another 25 sx "C" cel e surface'. Set a regulation 4" x 4' dry h	e of starting any proposed work. If well is s work.)" Spot 25 sx "H" cement above oint. By wireline, cut 4" liner ross the 8-5/8" intermediate rump 80 sx "C" cement into the ment in the casing from 550' - 450' ole marker.

*See Instruction on Reverse Side

J GWW

NADEL AND GUSSMAN PERMIAN

Champeau Federal #1

660' FNL, 1980' FWL, UnitC, Sec 31, T15S, R30E, Chaves County, NM

API # 30-005-00518



TD @ 11,250'

Former Well Name: Texaco - Shell Champeau Federal #1 Spud Date: 05/03/62, P&A 7/05/68, reentered 3/27/85 RTM

NADEL AND GUSSMAN PERMIAN

Champeau Federal #1

660' FNL, 1980' FWL, UnitC, Sec 31, T15S, R30E, Chaves County, NM

API # 30-005-00518

Elev: 3932' GL



TD @ 11,250'

Former Well Name: Texaco - Shell Champeau Federal #1 Spud Date: 05/03/62, P&A 7/05/68, reentered 3/27/85 RTM