

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Union Oil Company of California		Address 205 East Washington, Lovington, N.M.	
Lease South Caprock Queen Unit Tract 47	Well No. 16-19	Unit Letter P	Section 19
Date Work Performed Jan. 6, 1963	Pool Caprock Queen	Township 15-S	Range 31-E
County Chaves			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain): **Conversion of well to water injection service**
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Pulled rods and tubing.
 Cleaned out to ETD of 3160'.
 Ran 3121' of 2" ome, 8rt, J-55 plastic lined tubing to 3128' with tension packer on bottom. Set packer with 10,000# tension.
 Placed well on water injection on Jan. 6, 1963. Initial rate 813 bbls/day at 0 psig.
 Authority: Administrative Order No. WFX-124 dated 12-14-62.

Witnessed by Richard H. Butler	Position Unit Engineer	Company Union Oil Company of California
--	----------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY


D F Elev.		T D		P B T D		Producing Interval		Completion Date	
Tubing Diameter		Tubing Depth		Oil String Diameter		Oil String Depth			
Perforated Interval(s)									
Open Hole Interval				Producing Formation(s)					

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name ORIGINAL SIGNED BY RICHARD H. BUTLER
Title	Position RICHARD H. BUTLER Unit Engineer
Date	Company Union Oil Company of California

1. The first step is to identify the problem. In this case, the problem is that the system is not working properly.