_1			
Submit 3 Copies to Appropriate District Office		New Mexico Natural Resources Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM \$8240 OIL CONSERVATION DIVISION			
310 Old Santa Fe Trail, Room 206			WELL API NO. 30-005-10031
P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lesse No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
			7. Lease Name or Unit Agreement Name
1. Type of Well:			State 28
WELL X WELL 2. Name of Operator	OTHER		
Chaveroo Ope	erating Company,	Inc.	8. Well No.
3. Address of Operator P.O. Box 54'	75 Kingwood	Texas 77325	9. Pool name or Wildcat
4. Well Location			Tobac Penn
Unit Letter :	1874 Feet From TheF	NL Line and 554	Feet From The FWL Line
Section 28	Township 8-5	Range 33-E	NMPM Chaves County
	10. Elevation (Short	w whether DF, RKB, RT, GR, etc.) 4383 GR	
11. <b>Che</b>	ck Appropriate Box to Ind		mont or Other Data
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PLUG AND ABANDON		
	CHANGE PLANS		
	]	CASING TEST AND CEN	
OTHER:			
12. Describe Proposed or Completed (	nexting (Classic and all and all		
12 Describe Proposed or Completed Operations (Clearly sate all periment details, and give periment date, including, estimated date of starting any proposed work) SEE RULE 1103. Started 11/12/94 Finlshed 11/17/94 Finlshed 11/17/94 Run cast iron bridge plug on wire line, set @ 9000', free point casing @ 3700' Circulate hole with mud, spot 25 sacks cement on top of cast iron bridge plug 9000'-8855', pull tubing to 7000', spot 25 sacks cement from 7000'-6855'. Pull tubing out, cut 4½" casing @ 3700'. Run tubing to 3750', spot 65 sacks cement, wait on cement, tag cement @ 3586', plug from 3750'-3586', perforate @ 1500'; try to circulate, could not pump into perforations, run tubing to 1560', spot 40 sacks cement. Tag cement @ 1368', plug from 1560'-1368'. Pull tubing to 60', pump 15 sacks from 60' to surface, pump 30 sacks down 13 3/8, Cement marker. Class "C" cement; Mud 25 lbs salt gel per bbl.			
		OK	'd by Jack Griffin OCD
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE SI S. Sung	Wary	Production	
TYPE OR FRINT NAME T.	G. Singletary		Mobile (505) 369-5776 TELETHONE NO. (505) 396-4338
(This space for State Use) APPROVED BY <u>APPROVAL</u> & ANY:	ffin		INSPECTOR JALL TOD

.

## RECEIVED

NOV Z 9 1994 OCD HOBBS OFFICE