

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL CONS. DIST.
HOBBS, NEW MEXICO 88240

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Texaoc Inc.	8. FARM OR LEASE NAME Peery Federal
3. ADDRESS OF OPERATOR PO Box 728, Hobbs, New Mexico 88240	9. WELL NO. 4
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface	10. FIELD AND POOL OR WILDCAT Little Lucky Lake Morrow
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 29, T15S, R30
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3999' DF	12. COUNTY OR PARISH Chaves
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETION ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☐
(Other) ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Cover all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) MIRU. Install BOP. Pull tubing and packer.
- 2) GIH with cement retainer. Set at $\pm 10,000'$.
- 3) Squeeze existing perfs 10,024'-038' with 150 sxs. Class "H" cement.
- 4) GIH with tubing and packer. Spot 200 gallons 10% acetic acid across prospective pay interval. Set packer at $\pm 9800'$. Load backside.
- 5) Swab fluid level down to 1500'.
- 6) Perforate 9883'-9894' with 1 11/16" thru tubing gun with 2 JSPP using high penetration charges (12', 24 holes).
- 7) Acidize perfs 9883'-9894' with 1000 gallons 7 1/2% Moroflow acid and 25,000 scf N2. (5000#, 2 BPM).
- 8) Swab to flow.

RECEIVED
OCT 6 11 11 AM '87
CARLOS J. TORRES
AREA SUPERINTENDENT

18. I hereby certify that the foregoing is true and correct 397-3571

SIGNED J. A. Hoar

TITLE Hobbs Area Superintendent DATE 10/02/87

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
PETER W. CHESTER

OCT 9 1987

*See Instructions on Reverse Side

RECEIVED

OCT 12 1987

OCD
HOLBS OFFICE