

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name B. D. Taylor
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>28</u> TOWNSHIP <u>15-S</u> RANGE <u>31-E</u> N.M.P.M.	10. Field and Pool, or Whidout Undesignated Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 4393' (GR)	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER <u>Perforate & Attempt Completion</u> ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

TOTAL DEPTH 13,540'
PLUG BACK TOTAL DEPTH 12,415'
13 3/8" OD 54.5# K-55 CSG SET @ 405'
8 5/8" OD 32# J-55 CSG SET @ 4086'
5 1/2" OD 17# S-95 & N-80 CSG SET @ 12,415'

1. Perforate 5 1/2" Csg W/2 JSPF From 12,314-12,324'.
2. Set pkr. @ 12,100' Swab well. Acidize perfs 12,314-12,324' W/1500 Gals 10% HCL Acid, 1500 gals CO₂ & 33 Ball Sealers.
3. Set CIBP @ 12,306' & spot 20' cement on plug. PBDT 12,276'.
4. Perforate 5 1/2" csg. W/2-JSPF From 12,242'-12,258'.
5. Acidize perfs 12,242-12,258' W/2600 gals 10% HCL & 2600 GALS CO₂.
6. Set RBP @ 12,223' & Pkr. @ 11,882'. Perforate 5 1/2" Csg W/2 JSPF From 12,186'-12,193'.
7. Acidize perfs 12,186-12,193' W/2500 gals 10% HCL Acid, 4000 gals CO₂ & 24 Ball Sealers. Swab.
8. Set RBP @ 11,699' & Pkr. @ 11,428'. Perforate 5 1/2" Csg W/2 JSPF From 11,636-11,648'.
9. Acidize perfs 11,636-11,648' W/5000 gals 15% NE Acid & 50 Ball Sealers.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Bahr II TITLE Dist. Opr. Mgr. DATE 3-5-85

APPROVED BY Ronald M. [Signature] TITLE OIL & GAS INSPECTOR DATE SEP - 5 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAR -6 1985

O.C.S.
HOBBS OFFICE

10. Reset RPB @ 10,252' & Pkr. @ 9938'. Perforate 5½" Csg W/2-JSPF from 10,154-10,160'.
11. Acidize perfs 10,154-10,160' W/2500 gals 15% NEFE Acid & 30 Ball Sealers.
12. Reset RBP @ 5460' & pkr. @ 5251'. Perforate 5½" Csg W/2 JSPF From 5384-5391'.
13. Acidize perfs 5384-5391 W/2000 gals 15% NEFE Acid.
14. Set CIBP @ 12,150 & spot 35' cement on plug from 12,150-12,115'.
15. Set CIBP @ 10,100' & Spot 35' cement on plug from 10,100-10,065'.
16. Spot 11 Sx Cement plug from 8800-8700'.
17. Spot 11 Sx cement plug from 7500-7400'.
18. Spot 11 SX Cement plug from 5450-5350'.
19. Set CIBP @ 5325' & spot 11 sx cement plug from 5325-5225'.
20. Spot 11 sx cement plug from 4150-4050'.
21. Spot 11 sx cement plug from 1200-1100'.
22. Spot 11 sx cement plug from 450-350'.
23. Spot 10 sx cement plug @ surface. Install Dry hole marker. Clean location. Well P&A 2-17-85

RECEIVED

MAR -6 1985

O.C.B.
HOUSE OFFICE