

OPERATIONS PLAN

OGS OPERATING CO., INC.

Fat Nose "27" Fed #1

1. Drill a 12 1/4" hole to approximately 320'.
2. Run 8 5/8" 24.0 ppf K-55 ST&C casing. Cement with 200 sx Class "C" cement containing 2% CaCl₂. Run centralizers on every other joint above the shoe. Apply thread lock to bottom two joints and guide shoe.
3. Wait on cement for six hours prior to cutting off.
4. Nipple up and install a 3000 psi. Double Ram and Annular BOP system with choke manifold. WOC 18 hours prior to drilling out.
5. Test BOP system to 1500 psi with the rig pump. Test casing to 1500 psi.
6. Drill 7 7/8" hole to 3550'. Run logs.
7. Either run 3550' of 4 1/2" 10.5 PPF LT&C casing and cement with 450 sx "Light" followed by 200 sx Class "C" with 2% gel or plug and abandon as per BLM requirements.

Exhibit "A"
OGS Operating Co., Inc.
Fat Nose "27" Fed #1
Section 27, T-7-S, R-30-E
Chaves County, New Mexico

