Submit 3 Copies To Appropriate Distric	<b>- 11</b>	New Mexico	~~*	FOIH C-103	
Office <u>District I</u>	<b>3.</b> .	and Natural Resources	WELL API NO.	evised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240			30-025-00263	,	
District II 1301 W. Grand Ave., Artesia, NM 882	10	ATION DIVISION		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 8741	^	St. Francis Dr.	STATE	FEE	
District IV	Santa Fe	, NM 87505	6. State Oil & Gas I	ease No.	
1220 S. St. Francis Dr., Santa Fe, NM					
87505 SUNDRY N	OTICES AND REPORTS ON	N WELLS	7. Lease Name or U	nit Agreement	
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVOIR. USE "AF PROPOSALS.)	Name:	Name: North Caprock Queen Unit			
1. Type of Well:	North Caprock Queen	Oint			
Oil Well X Gas Well	0. 11/-11 N/-				
2. Name of Operator State of New Mexico Oil Cons	8. Well No.	8. Well No.			
3. Address of Operator	8. Pool name or Wi	8. Pool name or Wildcat			
1625 French Dr., Hobbs, NM	88240		Caprock Queen North	Caprock Queen North	
4. Well Location					
Unit Letter	: 1650 feet from the	North line and	1980 feet from th	ne <u>West</u> line	
Section &	Township	13S Range	32E NMPM	County Lea	
		vhether DR, RKB, RT, G	R, etc.)		
	<u> </u>	1 NY CNY		A-	
	ck Appropriate Box to In	dicate Nature of Not	SUBSEQUENT REPO	III NDT ()E+	
	F INTENTION TO: (☐ PLUG AND ABANDON	<b>   </b>		TERING CASING	
PERFORM REMEDIAL WORK	LI PLUG AND ABANDON	X KEWILDIAL V	TOTAL D AL		
TEMPORARILY ABANDON	☐ CHANGE PLANS		AE	UG AND  BANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TES			
OTHER:		OTHER:			
12 Describe proposed or com	oleted operations. (Clearly sta	ate all pertinent details, a	nd give pertinent dates, inclu	ding estimated date of	
starting any proposed work recompilation.	). SEE RULE 1103. For Mul	Itiple Completions: Attac	ch wellbore diagram of prop	osed completion or	
OCD proposes to P&A per	the attached procedure.				
COP Proposition 1	•				
	TUE COM	MCCIONI ALICT DE MICE			
		aission must be not Ior to the beginn			
		OPERATIONS FOR TH			
	TO BE APPI	roved.			
I hereby certify that the information	ation above is true and comple	ete to the best of my know	vledge and belief.		
i hereby certify that the informa-	mon above is true and comple	to to the boot of my large.			
SIGNATURE	THE D.	Oil P. Can Immonton	DATE		
	TITLE_ Dept	ury On & Gas Inspector_	BATE	<del> </del>	
Type or print name Gary \			Telephone No. (505) 393-6		
Type or print name Gary V (This space for State use)	Wink		Telephone No. (505) 393-6	161	
(This space for State use)	Wink		Telephone No. (505) 393-6	161	
	Wink			161	

### Typical Well Plugging Procedure Sierra Blanca Orphan Wells

#### Basis of Plugging Design:

Review of the well files resulted in the following information about the condition of the wells and what is needed to properly plug them:

Surface casing: 7" – 10 3/4" set at approximately 300' and cemented with 150 sacks.

Benterra has assumed that these casing strings were cemented all the way to surface. Not all of the well files contained this information, but many did confirm that cement was circulated.

Base of Fresh Water: Paul Kautz advised that the base of fresh water was at approximately 300' in this area. Benterra has assumed that the base of fresh water is at the surface casing setting depth or at a minimum of 250'.

Production Casing: 4 ½" to 7" set at approximately 3000' and cemented with 600 sacks. The top of cement was recorded on only a very few wells; however, many permits contained the requirement that the casing strings be cemented through the top of the salt section, which occurs at approximately 1500' in this area. Several temperature surveys were run and confirmed this. Benterra has assumed that all of the production casing strings are adequately cemented at least through the salt section as the OCD required at the time they were drilled.

#### **Typical Plugging Procedure**

Make sinker bar run to check for obstructions and TD

Displace or circulate wellbore with fresh water

Surface pour a bentonite plug from TD to at least 100' above the production casing shoe or top perforation

RIH with a wiper plug and set 50' below top of salt

Surface pour a bentonite plug from 50' below to at least 50' above the top of salt RIH with wireline and perforate 50' below the surface casing shoe (minimum perf depth is 300')

RU cementer and squeeze/circulate cement from surface down production casing to provide for a 100' min plug behind the production casing

Leave production casing full of cement to surface and shut in

Dig out and cut off wellhead and install dry hole marker

Pack annulus with bentonite

Attempt to locate and cut off deadmen

Clean up location including any above-ground cement foundations

# **ENIERA** Corporation Mid-Continent Region

## WELL PLANNING SHEET PROPOSED P&A

Well Name: API Number: Coordinates: S - T - R County / State:	North Caprock Queen Unit # 8 30-025- ? (650' FNL + 1980' F S 8 - T13S - R32E Lea, New Mexico	·	Operator Field: Date: By:	OCD 7/19/02 CRS
Drilled:	1947	Pack annulus with ZO	NITE	
RKB = <u>8' ?</u>	• •		Surface Plug @3'- 206 Pump 38 sx cr	nt .
Formation T	lb20`_		Shoe Plug @ 206' - 30 Perf & Sqz @ 306' w	<b>Xo'</b> / <u>49</u> sx cmt
ZONITE/CEMEN	IT PLUGS 3'- 206'		Casing Size 10 <sup>3</sup> 4 Wt_ Set @ 256 W/ 150 Cemented to Surf (V	38# 25x cmt ")
(cement)  Shoe 2 (cement)  Salt (Sonite)	06'-306' 70'-1670' 935'-3085'		Salt Plug (ZONITE) @ <u>1570</u> _ <u>2</u> + _ cu ft ZONITE Wiper Plug @ <u>1670</u>	o'- 1670'
Legend Cement ZONITE Gravel				
Bottom _ <b>36</b>	Plug (ZONITE) @ <u>2935                                    </u>	тр 3085'	Casing Size [" Wt Set @ 3035' w/ G Cemented to surface  Will re-check  Internal plugs  sufficient ex  cement was	only if