

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND	FILE
OFF	OR

NEW MEXICO OIL CONSERVATION COMMISSION

Form O-103
 Overhauls Old
 O-102 and O-101
 Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A WELL TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM O-101) FOR SUCH PROPOSALS.)</small></p>		<p>1. Indicate Type of Notice</p> <p>Drill <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p>
<p>2. State Oil & Gas Lease No.</p> <p align="center">B-10077</p>		<p>3. Field or Lease Name</p> <p>New Mexico 'BV' State</p>
<p>4. Name of Operator</p> <p>TEXACO Inc.</p>		
<p>5. Address of Operator</p> <p>P.O. Box 728, Hobbs, New Mexico 88240</p>		<p>6. Well No.</p> <p align="center">1</p>
<p>7. Location of Well</p> <p>UNIT LETTER E 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 13-S RANGE 33-E NMPM.</p>		<p>8. Field, Pool, or Wildcat</p> <p align="center">Lazy J Penn</p>
<p>9. Elevation (Show whether DF, RT, GR, etc.)</p> <p align="center">4216' DF</p>		<p>10. County</p> <p align="center">Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING Casing <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OR OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CELEST JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent measurements, etc. for each proposed work) SEE RULE 1103.

1. Pull injection equipment.
 2. Load hole with mud (25 sxs gel per 100 bbls. water).
 3. Set CIBP at 9090 and spot a 20' (2 sx) cement plug on top. → 35' min. plug required.
 4. Run freepoint, cut 5 1/2" casing and pull.
 5. Spot 100' (20 sx) cement plug across casing stub, 50' above and 50' below.
 6. Spot 100' (35 sx) cement plug across intermediate casing shoe at 4059'.
 7. Spot 10' (4 sx) cement plug at surface.
 8. Install marker and clean location.
- Handwritten notes:*
 { 100' plug at top Abn } if not
 { 100' plug at top Florita } behind
 { 100' plug at top salt. } casing.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED <u><i>John Runyan</i></u>	TITLE <u>Assistant District Supt.</u>	DATE <u>August 4, 1975</u>
APPROVED BY <u><i>John Runyan</i></u> Geologist	TITLE <u>Geologist</u>	DATE <u>AUG 6 1975</u>

CONDITIONS OF APPROVAL, IF ANY: