

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator TEXACO Inc.	5. State Oil & Gas Lease No. B-10077
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240	7. Unit Agreement Name
4. Location of Well UNIT LETTER K 1981 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 13-S RANGE 33-E NMPM.	8. Farm or Lease Name New Mexico 'BV' St. (NCT-1) 9. Well No. 1 3
15. Elevation (Show whether DF, RT, GR, etc.) 4220' DF	10. Field and Pool, or Wildcat Lazy J Penn
12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>



SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull stuck tubing.
2. Load hole with mud (25 sx gel per 100 bbls water).
3. Set CIBP at 9078' and spot 35' (4 sx) cement plug on top.
4. Ran freepoint, cut 5 1/2" casing and pulled 4045'.
5. Spot 200' (50 sx) cement plug 4095'-3895'.
6. Spot 100' (35 sx) cement plug 1400'-1300'.
7. Spot 10' (10 sx) cement plug at surface.
8. Install dry hole marker and clean location. Well P & A 5-28-76.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Asst. Dist. Supt.	DATE June 3, 1976
APPROVED BY 	TITLE Geologist	DATE JUL 14 1976
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUN 2 1976

U.S. CONSERVATION COMM.
HOBBS, N. M.