

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND	FILE	
OPER	OR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form O-103
Revised 6-64
O-102 and O-103
Effective 1-1-65

5. Estimate Type of Work Drill <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
6. State Oil & Gas Lease No. B-10077
7. Unit Agreement No.
8. Name of Lessee New Mexico "BV" State
9. Well No. NCT-1
10. Field No., Pool, or Well Unit 5
11. Field Name Lazy Penn
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM O-101) FOR SUCH PROPOSALS.)

1. Name of Operator TEXACO Inc.	2. Nature of Work Water Injection
3. Address of Operator P.O. Box 728, Hobbs, New Mexico 89240	
4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 26 TOWNSHIP 13-S RANGE 33-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4427' DF	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CEMENT <input type="checkbox"/>
COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, to the extent possible, for the proposed work) SEE RULE 1103.

1. Load hole with mud (25 sx gel per 100 bbls. water).
2. Set CIBP at 9550' and spot a 20' (2-sx) cement plug on top. → 35' min. plug required
3. Ran freepoint, cut 5 1/2" casing and pull.
4. Spot 100' (20 sx) cement plug across casing stub.
5. Spot 100' (30 sx) cement plug across intermediate casing shoe at 4066.
6. Run freepoint, cut 8 5/8" casing and pull.
7. Spot 100' (45 sx) cement plug across casing stub.
8. Spot 100' (65 sx) cement plug across surface casing shoe at 351'.
9. Spot 10' (7 sx) cement plug at surface.
10. Install marker and clean location.

100' plug at top Abo.
100' plug at top Gloria } if not behind casing.
100' plug at top Split

18. I hereby certify that the information above is true and complete to the best of my knowledge.

SIGNED [Signature]
Original Signed by
John Runyan
Geologist

TITLE Assistant District Supt.

August 4, 1975

APPROVED BY _____

TITLE _____

CONDITIONS OF APPROVAL, IF ANY: