HD. OF COPIES RECEIVED DISTRIBUTION SANTA FE FILE	NEW	MEXICO OIL CONSE	RVATION COMMISSION		Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
U.S.G.S.					Sa. indicate Type of Lease
OPERATOR	1				State Fee X
	J				
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO CEILL OR TO DELETE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "TAPPLICATION FOR PERMIT -" (FORM CLIDIT OR SUCH PROPOSALLO)					
	07 H E R -				7. Unit Agreement Name
1. Name of Operator					8, r urm or Lease Hame
Cities Service Oil and Gas Corporation					Turner D
3. Address of Operator					9. Well No.
P.O. Box 1919 - Midland, Texas 79702					1
4. Location of Well					10. Field and Pool, or Wildcat
UNIT LETTER N		South	1980	FEET FROM	Gladiola Dev., Southwes
	ом <u>27</u>	TOWNSHIP 125	<u>37E</u>	NMPM.	
15. Elevation (Show whether DF. RT. GR. etc.) 3895' GR					12. County Lea
	Appropriate E NTENTION TO		ature of Notice, Repo subs		ner Data r report of:
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON		CHANGE PLANS	COMMENCE DRILLING OPNS. Casing test and cement jo		PLUG AND ABANDONMENT
other Locate and squee	eze casing]	leak X	OTHER	<u></u>	

17. Describe Proposed of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

O.T.D. 12,288' Dolomite. It is proposed to locate and cement a casing leak in the following manner:

- 1. MIRU pulling unit, install BOP and pull tubing, packer and jet pump.
- 2. RIH w/RBP & RTTS on 2-7/8" tubing and set RBP @ approx. 9130' and set RTTS @ approx. 9100'. Test RBP to 1000#. Reset RTTS at various depths to locate leak in 5-1/2" casing. Establish IR into leak. POOH w/RTTS and RBP.
- 3. Set a CIBP @ approx. 9130'. RIH w/5-1/2" cement retainer on 2-7/8" tubing and set retainer @ approx. 6400'. Test tubing to 4000# and annulus to 1000#. Establish IR and squeeze casing leak w/150 sacks of Class C Neat cement. Pull out of retainer and reverse out excess cement. POOH w/tubing.
- 4. RIH w/RB and DC's on 2-7/8" and test casing to 1000#. Drill out cement retainer and cement to 9130'. CHC. Test squeeze to 1000#. Drill out CIBP set @ approx. 9130'. CHC and POOH.
- 5. RIH w/2-7/8" tubing and packer and set packer @ approx. 9125'. ND BOP and NU WH. Circulate hole and drop SV and jet pump and start well pumping.

12. I hereby certify that the information above is true and complet	e to the best of my knowledge and belief.	_
STENED Elmer Startz	Reg. Opr. Mgr Prod.	6-21-83
THOMMAL DESMAD BY JERRY SEXTOM DESTRICT (SUPERVISOR CONDITIONS OF APPROVAL, IF ANY:		JUN 2 3 1983