

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

1001 10 17 11 67

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Depleted</u>	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name HOUSTON "A"
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 2
4. Location of Well UNIT LETTER <u>L</u> <u>2110</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>330</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>19</u> TOWNSHIP <u>12-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat GLADIOLA WOLF CAMP
15. Elevation (Show whether DF, RT, GR, etc.) 3875' GL	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
---	---	---	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109.

Zone has been depleted. Workover and recompletion possibilities are nil. Prepare to P+A as follows:

1. Spot 15 cu. Cement plug 9100-9600 (perms 9630'-44')
2. Cut and pull 5 1/2" casing @ free point. Est 5500'. Spot 25 cu in & out of stab.
3. Spot 20 cu plug in & out of 9 5/8" CSA 4500'.
4. Cut & pull 9 5/8" log @ free point. Est 1200'. Spot 25 cu. In & out of stab.
5. Spot 20 cu plug in & out of 13 3/8" csq @ 316'.
6. Spot 10 cu at surface and Erect P+A marker.
7. Make final cleanup and restore ground to contour.

TD - 9816'
PBD - 9766'
PERM - 9630-44'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE AREA SUPERINTENDENT DATE 10-6-67

0+ 2-NMOCC-M
1-NSU

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

1-SUSP
1-RRY