

Form C-103  
Revised 10-1-7

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
B-9505

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Texaco Inc.		8. Farm or Lease Name New Mexico "AT" State	
3. Address of Operator PO Box 728, Hobbs, New Mexico 88240		9. Well No. 7	
4. Location of Well UNIT LETTER <u>B</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>14S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Saunders Permo Upper Penn	
15. Elevation (Show whether DF, RT, GR, etc.) 4215' DF		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
<input type="checkbox"/> (a) Sell or dispose of the property	<input type="checkbox"/> (a) Sell or dispose of the property
<input type="checkbox"/> (b) Transfer the property to another person	<input type="checkbox"/> (b) Transfer the property to another person
<input type="checkbox"/> (c) Lease the property to another person	<input type="checkbox"/> (c) Lease the property to another person
<input type="checkbox"/> (d) Mortgage the property	<input type="checkbox"/> (d) Mortgage the property
<input type="checkbox"/> (e) Other	<input type="checkbox"/> (e) Other

PERFORM REMEDIAL WORK	<input checked="" type="checkbox"/>	PLUG AND ABANDON	<input type="checkbox"/>	REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>			COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>	CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER _____	<input type="checkbox"/>			OTHER _____			<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1(f)(3).

- 1) MIRU pulling unit. Install BOP.
- 2) RIH with swage on 2 3/8" workstring. Swage out tight spot in casing at 7470'. Lower swage to 7909'. (Top of fish at 7910'.) POH.
- 3) Fish rods and tubing. POH.
- 4) RIH with gauge ring to  $\pm$  9700'. RIH with 4 1/2" CIBP and set at  $\pm$  9700'.
- 5) RIH with 4 1/2" packer on workstring. Test CIBP to 2000 psi. Locate and isolate casing leaks with packer. (Suspected leak at 7470'.) Test backside to 500 psi.
- 6) RIH with drillable cement retainer and set above casing leak.
- 7) Squeeze casing leak to 2000 psi with 200 sxs. of Class "H" neat cement.
- 8) Drill out cement retainer and cement to top of CIBP. Test casing to 500 psi.
- 9) If casing does not test satisfactorily, run a Pipe Analysis Log from PBTD to 4000'.
- 10) Resqueeze casing as necessary until casing tests satisfactorily.
- 11) Drill out cement and CIBP. Clean out to PBTD (9967'). POH. (OVER)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

397-3571

SIGNED H. A. Hobbs TITLE Hobbs Area Superintendent

DATE August 18, 1987

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY 4.

**TITLE**

CONDITIONS OF APPROVAL, IF ANY:

**AUG 25 1987**

- 12) RIH with 4 1/2" packer on workstring to  $\pm$  9951'. Spot 150 gals. of scale converter from 9720'-9951'. Set packer at  $\pm$  9700'. SION.
- 13) Swab back scale converter. Release packer. Spot 150 gals. of 15% NEFE acid from 9720'-9951'. Set packer at  $\pm$  9670'. Load backside. Pressure up on backside to 300 psi.
- 14) Acidize perfs 9767'-9951' (37 holes) with 5000 gals. of 15% NEFE acid containing 2 drums of scale inhibitor and 3 drums of Checkersol with 56 ball sealers. Max. rate and pressure: 3 BPM, 4000 psi. SION.
- 15) Swab back load, then return well to production.

RECEIVED  
AUG 21 1987  
OCD  
HOBBS OFFICE