NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
u.s.g.s.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR	1	5. State Oil & Gas Lease No.
		No record
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG PACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
USE "APPLICA	TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	<u> </u>
OIL GAS WELL	OTHER-	7. Unit Agreement Name Ranger Lake Unit
2. Name of Operator		8. Form or Lease Name
Phillips Petroleum Company		Ranger Lake Unit, Tracte
3. Address of Operator		9. Well No.
Room 711, Phillips Building, Odessa, Texas 79761		1
· · ·	660 FEET FROM THE South 1195 AND 660	10. Field and Pool, or Wildcat
UNIT LETTER,	660 FEET FROM THE SOUTH LINE AND 660 FEET FRO	Ranger Lake (Penn)
east	10N 27 TOWNSHIP 12-S RANGE 34-E	
THE LINE, SECT	ION TOWNSHIP RANGE NMP	~ (((((((((((((((((((((((((((((((((((((
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4152' Gr.	Lea
16. Check	Appropriate Box To Indicate Nature of Notice, Report or O	ther Deep
	NTENTION TO	T REPORT OF:
	0000000	THE ON TOT
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOE	PEOG AND ABANDONMENT
<u> </u>	OTHER	[-7
OTHER		
17 Congribe Ergrand or Completed O	Charles and a state of the stat	
work) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent dates, includir	ig estimated date of starting any proposed
10,290-358' w/50 sx 6 Load hole using 25 st 5-1/2" casing, cut at below to 50' above ca if cut is below 4300 tubing. With TOC bel point and recover. I cut. Cement volume	Relocate tubing in packer at approximately 1 Class H w/3/10% LWL and 1# Gilsonite per xx. For gel per 100 BW. Pull tubing. With estimated to free point and recover. Run tubing, spot 30 asing cut. If cut is below 5625', spot 50 sx color, spot 35 sx cement plug 4300-4200' across 8-5 mind 8-5/8" casing at approximately 3500', cut Run tubing, spot 75 sx cement plug f/50' below to be sufficient to protect base of salt. Spot so 13-3/8" casing shoe at 365'). Spot 10 xx plus	ick up out of packer.  TOC at 8500' behind  sx cement plug f/50'  ement plug 5625-5525';  /8" casing shoe. Pull  8-5/8" casing at free  8-5/8" cut to 50' above  100 sx cement plug
cc: Appoco Production	Company, Box 68, Hobbs, New Mexico 88240  above is true and complete to the best of my knowledge and belief.	
Marl 111	, who will be and be my knowledge and better.	
SIGNED Holler	W.J. Mueller Senior Reservoir Engineer	DATE 2-15-73
Or Or	s. Signed by	
Jo	D. Ramer	

CONDITIONS OF APPROVAL, IF ANY: