

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. E-9247	
7. Unit Agreement Name	
8. Farm or Lease Name New Mexico 'DA' State NCT-2	
9. Well No. 1	
10. Field and Pool, or Wildcat Ranger Lake Penn	
12. County Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator TEXACO Inc.
3. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 14 TOWNSHIP 12-S RANGE 34-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4165' (DF)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data



NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following work has been completed to plug and abandon subject well:

1. Pulled production rods and pump. Mud up hole.
2. Spot 25 sx cement plug from 10125 - 9750 (375' interval).
3. Cut and pull 4707' 4-1/2" OD 11.60# J-55 casing.
4. Spot 25 sx cement plug from 4757' to 4657' (100' interval).
5. Spot 25 sx cement plug from 4250' to 4150' (100' interval).
6. Spot 10 sx cement plug at surface (25' plug).
7. Install 4" dry hole marker extending 4' above ground level.
8. Clean location. Plug and Abandon.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Assistant District Superintendent	DATE August 10, 1970
APPROVED BY 	TITLE Geologist	DATE DEC 8 1970
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

AUG 1 1970

OIL CONSERVATION COMM.
HOES, N. H.