

In Appropriate
District Office

Energy, Minerals and Environment

DISTRICT
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT
P.O. Drawer DD, Artesia, NM 88210

DISTRICT
1000 Rio Grande Rd., Alamosa, NM 87110

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL ☒ GAS ☐ OTHER ☐

2. Name of Operator

Coastal Oil & Gas Corporation

3. Address of Operator

P.O. Box 235, Midland, Texas 79702

4. Well Location

Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line

Section 32

Township 13-S

Range 33-E

MMMM

Lea

County

10. Elevation (Show whether LF, RKB, RT, GR, etc.)

4263.8 Gr

WELL NO.

30-025-22357

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

K-4177

7. Lease Name or Unit Agreement Name

State "32"

8. Well No.

1

9. Pool name or Wildcat

South Basin
Wildcat Wolfcamp

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERMANENT REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
FULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

1. MIRU Baber Well Service on 7-30-92. LD rods and tbg.
2. Ran CIBP on WL, could not set plug, WL parted, fished WL.
3. Set CIBP on WL at 9010'. GIH with tbg, circ hole with 9.5 PPG mud.
4. Ran cmt bailer, spot 35' cmt plug on top of CIBP.
5. Worked 5-1/2" csg, showed to be free at 4800'. Shot csg at 4800', 4704', 4513'. Unable to move. RU WL, shot csg at 4411', pulled free.
6. POOH and LD 137 jts 5-1/2" csg.
7. GIH with tbg to 4850', spot 75 sack plug 4850-4340'. PU to 4090', WOC.
8. GIH, tag plug at 4394', pumped 20 sack plug.
9. POOH to 4093', pumped 50 sack plug, WOC, tag plug, not there.
10. Spotted 60 sack plug @ 4093'. PU, WOC, GIH and tag plug at 4002'.
11. POOH with tbg to 1600', spot 50 sack plug.
12. Weld onto 8-5/8" csg, cut 8-5/8" at 657', POOH and LD same.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bobby L. Smith TITLE Sr. Petroleum Engineer DATE 9-21-92

TYPE OR PRINT NAME Bobby L. Smith

TELEPHONE NO. 915 682-7925

(This space for State Use)

APPROVED BY Lyle F. Turnaciff TITLE OIL & GAS INSPECTOR DATE JAN - 6 1993

CONDITIONS OF APPROVAL, IF ANY:

Coastal States"32' #1

Page Two *BLSmith*

13. GIH with tbg to 700', spotted 50 sack plug, POOH.
14. GIH with tbg, tag plug at 600'. POOH to 402'.
15. Spotted 50 sack plug, POOH, WOC, GIH and tagged plug at 312'.
16. Spotted 10 sack surface plug.
17. Install P&A marker, clean and level location. Well P&A'd 8-19-92.