NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE	NEW MEXICO OIL CON	SERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			
U.S.G.S.	-		5a. Indicate Type of Lease
LAND OFFICE			State Fee X
OPERATOR			5, State Oil & Gas Lease No.
SUND	RY NOTICES AND REPORTS ON ROPOSALS TO DRILL OR TO DEEPEN OR PLUG TION FOR PERMIT - " (FORM C-101) FOR SUC	WELLS	
USE **APPLICA	TION FOR PERMIT -** (FORM C-101) FOR SU	BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)	
			7, Unit Agreement Name
WELL GAS WELL	OTHER.		
2. Name of Operator			8. Farm or Lease Name
Coastal States Gas Producing Company			Chambers
3. Address of Operator	· · · · · · · · · · · · · · · · · · ·		9. Well No.
P. O. Box 235, Midlan	id, Texas 7 9701		1
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER	1980 FEET FROM THE nor th	LINE AND 1980 FEET FRO	Undes. No. Baum (Penn)
THELINE, SECT	29 TOWNSHIP 13S	RANGE 33E NMPN	//////////////////////////////////////
			- ΛΗΗΗΗΗΗΗΗΗΗΗΗΗΗ
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
$\boldsymbol{\lambda}$	4259.7' GR		Lea
^{16.} Check	Appropriate Box To Indicate N	ature of Notice Report or O	ther Data
	INTENTION TO:		T REPORT OF:
		5005EQUEN	TREFORT OF.
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	• · · · · · · · · · · · · · · · · · · ·
		COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	CHANGE FLANS		ا ــــا
		OTHER	
OTHER	[

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well No. 1 was completed on 11-30-68 in the Baum (Upper Penn) pool. The well produced 100% water for 8 weeks and was temporarily abandoned. It is proposed to start plugging operations on approval. The procedure for plugging well will be as follows:

Set CI bridge plug @ 9720' and dump 10' cmt on top of plug. 1. Set 25 sx plug @ 5-1/2" csg stub. 2. Set 25 sx plug @ 5440' (top of Glorieta). 3. 4. Set 50 sx plug 4148-4018' in and out of 8-5/8" shoe @ 4083'. 5. Set 25 sx plug @ 1678' @ top of salt if exposed. 6. Set 25 sx plug @ 8-5/8" stub. 7. Set 25 sx plug 434-374' in and out of 13-3/8" shoe @ 404'. 8. Set 10 sx plug in top. 9. Install DHM.

18. I hereby certify that the information above is true and comple	te to the be	st of my knowledge and belief. Division Production Man	ager _{ate} Sept. 15, 1970
APPROVEDAY	TITLE	NO N	DATE SET 1 \$ 1970



SEP 17 1970