

RECOMMENDED WORK PROCEDURE

LEASE: STATE M COM
ANNULAR FLUID PRIOR TO WORKOVER:
FORMATION FLUIDS

WELL NO: 1
W/O FLUID TO BE USED:
9.5 LB/GAL MUD

PLEASE CONTACT OPERATIONS ENGR. IN HOBBS (393-9186) 24 HOURS
PRIOR TO MIRU

CONTACT NMOC D @ 393-6161 24 HRS BEFORE MIRU

1. MIRU. POH w/ RODS & PUMP.
2. NU BOPs. UNSEAT TA & POH w/ TBG
3. RIH w/ 5-1/2" 17# CIBP & SET @ 9900'. CAP w/ 35' CMT.
4. CIRCULATE HOLE w/ 9.5 LB/GAL MUD.
5. RIH w/ FREE POINT INDICATOR & LOCATE FREE POINT IN 5-1/2" CSG
6. CUT 5-1/2" CSG @ THE FREE POINT & POH w/ CSG.
7. CIRCULATE HOLE w/ 9.5 LB/GAL MUD.
8. SPOT 100' CMT PLUG (MIN 25 SX) ACROSS TOP OF 5-1/2" CSG STUB
(50' IN & OUT OF STUB TOP).
9. TAG CMT PLUG ON TOP OF 5-1/2" CSG STUB. RE-SPOT PLUG IF
NECESSARY.
10. SPOT 100' CMT PLUG (MIN 25 SX) ACROSS GLORIETTA FORMATION TOP
FROM 6245 - 6145'. (GLORIETTA TOP @ 6195')
11. SPOT 100' CMT PLUG (MIN 25 SX) ACROSS 9-5/8" CSG SHOE
FROM 4550 - 4450'. (9-5/8" CSG SHOE @ 4500')
12. TAG CMT PLUG TOP @ 4450'. RE-SPOT PLUG IF NECESSARY.
13. RIH w/ 4" CSG GUN & PERFORATE THE 9-5/8" CSG @ 2040' w/
PREMIUM CHARGES, 4 JSPF, 120 DEG PHASING. POH.
14. RIH w/ 9-5/8" 36# CMT RETAINER & SET @ 1940'. (50' ABOVE TOP
OF SALT FORMATION)
15. SQUEEZE PERFS @ 2040' w/ 600 SX CMT & CIRC CMT TO SURFACE
BETWEEN THE 9-5/8" & 13-3/8" CSG. PULL OUT OF CMT RETAINER
& SPOT 4 SX CMT ON TOP.
16. SPOT 100' CMT PLUG (MIN 25 SX) ACROSS 13-3/8" CSG SHOE
FROM 480 - 380'. (13-3/8" CSG SHOE @ 430')

NOTE: CMT PLUG MUST BE INSIDE AND OUTSIDE OF THE 9-5/8" CSG