

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-1 25-13 2 77

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

K-3643

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

State 1

1. Type of Well:

OL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Petroleum Production Management, Inc.

8. Well No.

2

3. Address of Operator

Suite 200/Sutton Place Bldg. Wichita, Kansas 67202

9. Pool name or Wildcat

Baum Upper Penn

4. Well Location

Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line

Section 1 Township 14-S Range 32-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Move in and rig up casing pulling rig.
- Set cast iron bridge plug in 5 1/2" casing at 9808', 50' above casing perforations from 9858' to 9894' and cap with 50' of cement. 100' plug @ 6850
- Load hole with salt gel mud.
- Shoot off 5 1/2" casing at free point estimated at 5000'.
- Pull and lay down 5 1/2" casing.
- Spot 50 sacks of cement plug from 50' inside 5 1/2" casing stub to form 150' cement plug straddling top of 5 1/2" casing. Tag top of cement.
- Spot 100' cement plug in 8 5/8" across casing shoe at 4015'. Tag top of cement.
- Shoot off 8 5/8" casing at free point and lay down 8 5/8" casing.
- Spot 70 sack cement plug from 50' inside 8 5/8" casing. Tag top of cement.
- Spot 70 sack cement plug at 478', 50' below 11 3/4" casing shoe at 428'.
- Spot 10 sacks of cement in 11 3/4" casing at surface. Erect dry hole marker.
- Clean and level location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gary T. Cothran TITLE District Superintendent DATE 12-11-90

TYPE OR PRINT NAME Gary T. Cothran TELEPHONE NO. 675-2478

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL: IF ANY