NEW MEXICO OIL CONSERVATION COMMISSION New Mexico Ne		and the control of th		
NEW MEXICO OF CONSERVATION COMMISSION Continue Type of Lease Sun Defice Sun Constitute Type Sun Const				
SUNDRY NOTICES AND REPORTS ON WELLS OFF. WELL 1. OFF. WELL 2. NAME of Operator SUNDRY NOTICES AND REPORTS ON WELLS OFF. WELL 2. NAME of Operator 1. Out Agreement Name American Quasar Petroleum Co. of New Mexico 1. Actess of Operator 1. Out Midland National Bank Tower, Midland, Texas 79701 1. Out off. West Completed Operators of Sundry Survey of Sundry Sun			•	
Substitute Type of Lease State Sta		MEW MEXICO OIL CONSERVATION COMMISSION	Difective 1-1-55	
SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICES AND REPORTS ON WELLS CONTROL OF USE TRIBE SUNDRY NOTICE OF USE TRIBE SUNDRY NOTICE OF USE TRIBE SUNDRY NOTICE OF INTENTION TO: CHECK Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: CHECK Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: CHARGE FLANK CHARGE			In Indiana Type of Lance	
SUNDRY NOTICES AND REPORTS ON WELLS One of the content of the c				
SUNDRY NOTICES AND REPORTS ON WELLS Comparison Compa				
Secretary Secr			1	

American Quasar Petroleum Co. of New Mexico 1. Address of Operator 1. LOOM Midland National Bank Tower, Midland, Texas 79701 1. Location of Wall 1. Location (Show whether DF, RT, GR, etc.) 1. Location (Show whether DF, RT, GR, etc.) 1. Location (Show whether DF, RT, GR, etc.) 1. Location North Bagley 1. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: 1. Location Notice OF Intention (Show whether DF, RT, GR, etc.) 1. Location Notice OF INTENTION TO: 1. Location Notice OF INTENTION TO: 1. Location Notice OF INTENTION TO: 1. Location Notice OF Intention (Show whether DF, RT, GR, etc.) 1. Location Notice OF Intention of Other Data 1. Location Notice Report of Other Park And Calment Park And Calment Park And Calment Park And Calm	WELL X	WELL OTHER-	7, Unit Agreement Name	
1. Addiess of Operator 1. 1000 Midland National Bank Tower, Midland, Texas 79701 4. Location of Well West Line and 510 rest room North Line, section 15 rownship 12 - S rance 33 - E rank North Line, section 15 rownship 12 - S rance 33 - E rank RKB 4270' 16. Check Appropriate Box To Indicate Nature of Notice, Report of Other Data Notice of Intention to: **Red 4270' **Red 4270' RCB 4270' **Red 42	•		8. Fam or Lease liame	
1000 Midland National Bank Tower, Midland, Texas 79701 4. Loccitan of Well West Line and 510 rest from the West North Bagley North Line, section 15 rowsenip 12 - S same 33 - E maps. 12. County Leg RKB 4270' Check Appropriate Box To Indicate Nature of Notice, Report of Other Data NOTICE OF INTENTION TO: PLUG AND ADANDON SUBSEQUENT REPORT OF: PLUG AND ADAND			Humble State	
15. Elevation (Show whether DF, RT, CR, etc.) 12. County 12. County 14. County 15. Elevation (Show whether DF, RT, CR, etc.) 12. County 14. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent Report of Subsequent			9. Well No.	
North Line, Section 15 township 12 - S sakes 33 - E super. North Line, Section 15 township 12 - S sakes 33 - E super.	1000 M	idland National Bank Tower, Midland, Texas 79701	1	
15. Elevation (Show whether DF, RT, GR, etc.) 12. County 12. County 16. 16. 16. 16. 17. 16. 16. 16. 16. 17. 16	4. Location of Wel			
15. Elevation (Show whether DF, RT, GR, etc.) RKB 4270' 12. County Lea NOTICE OF INTENTION TO: PLUC AND ABANDON TEMPORAL WORK TEMPORALITY ABANDON PULL DA ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. 12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 10 sack plug at surface. Installed dry hole	UNIT LETTER _	D . 660 PEET FROM THE West LINE AND 510 PEET FROM	North Bagley	
15. Elevation (Show whether DF, RT, GR, etc.) RKB 4270' 12. County Lea NOTICE OF INTENTION TO: PLUC AND ABANDON TEMPORAL WORK TEMPORALITY ABANDON PULL DA ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. 12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 10 sack plug at surface. Installed dry hole	THE N	orth Line, Section 15 Township 12 - S BANGE 33 - E		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PLUC AND ABANDON FULL DR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposed or Moved on location. POH with tubing and rods. 12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORAMIC PLANS CHARGE PLANS CHARGE PLANS CASING TEST AND CEMENT JQB OTHER 17. Destribe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see RULE 1763. 12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole			12. County	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PLUC AND ABANDON PULL ON ALTER CASING TEMPORAM REMEDIAL WORK CHANGE PLANS CHANGE PLANS TOTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose 12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 360'. WOC and tagged. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	İmmi	11111111111111111111111111111111111111	Lea (IIIIIIII	
PULL OR ALTER CASING CHARGE PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS CASING TEST AND CEMENT JUGG CHARGE PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS CHARGE PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CHARGE PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CHARGE PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CHARGE PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CHARGE PLANS CHARGE PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CHARGE PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CHARCH PLANS CHARCH PLANS CASING TEST AND CEMENT JUGG CHARCH PLANS CASING TEST AND CEMENT JUG		MOTICE OF INTENTION		
Pull on Alter Casine There T	PERFORM REMEDIA	L WORK PLUG AND ABANDON REMEDIAL WORK	DAIRAS BAIRSTLA	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE NULE 1769. 12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	TEMPORARILY ABAR	DON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. 12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	PULL OR ALTER CA	SING CHANGE PLANS CASING TEST AND CEMENT JQ8		
12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole		OTHER		
12-29-77 Moved on location. POH with tubing and rods. 12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	STHER			
12-30-77 Run CIBP and set @ 8750' and capped with 35 ft. cement. 1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	17. Describe Prop work) SEE RU	osed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including UE 1703.	estimated date of starting any propose	
1-4-78 Cut 5-1/2" casing @ 5017'. Pulled and layed down. 1-5-78 Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8" casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	12-29-77	Moved on location. POH with tubing and rods.		
Run tubing to 5196' and spotted a 45 sacks to 4932'. WOC 4 hrs. and tagged. Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8' casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	12-30-77	Run CIBP and set @ 8750' and capped with 35 ft. cement.		
Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with tubing. 1-6-78 Cut 8-5/8'' casing @ 1100' and POH. 1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	1-4-78	Cut 5-1/2" casing @ 5017'. Pulled and layed down.		
1-7-78 Run tubing to 1139' and spotted a 45 sack plug to 1030' and WOC - tagged plug. Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	1-5-78	Pulled tubing to 3894' and spotted a 35 sack plug to 3792'. WOC. Tagged on 1-6-78. Pulled tubing to 1767' and spotted a 35 sack plug to 1667'. POH with		
Pulled tubing to 465' and spotted a 75 sack plug to 360'. WOC and tagged. 1-7-78 Cut off well head and spotted a 10 sack plug at surface. Installed dry hole	1-6-78	Cut 8-5/8" casing @ 1100' and POH.		
The state of the s	1-7-78	Run tubing to 1139' and spotted a 45 sack plug to 1030' and Pulled tubing to 465' and spotted a 75 sack plug to 360'. W	WOC - tagged plug. C and tagged.	
	1-7-78	Cut off well head and spotted a 10 sack plug at surface. In marker and moved off location.	stalled dry hole	
		•	•	

OIL & CAS INSPECTOR

1 - 11 - 78

OCT 17 1983

RECEIVED

JUL 1 7 1380

The dispersation by.