

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
9. Well No.	
10. Field and Pool, or Wildcat	
12. County	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator
3. Address of Operator	4. Location of Well
UNIT LETTER <u>A</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>12-S</u> RANGE <u>33-E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MI casing pulling rig.
  2. Pull 2-1/2" tubing
  3. Set CIBP on wire line @8700' and dump 10' cement plug.
  4. Run tubing and displace well bore fluids w/10# mud laden brine. Pull tubing.
  5. Strap weld lift nipple, work 5-1/2" casing, cut off @ free point (TC 6005') and pull 5-1/2" casing.
  6. Run tubing and spot 100' cement plug top of cut off.
  7. Pull tubing and spot 100' cement plug at shoe of 8-5/8" casing @ 3900'. Pull tubing.
  8. Strap weld 1' nipple, work 8-5/8" casing and cut off @ free point - Pull 8-5/8" casing (Approx. 1500').
  9. Run tubing and spot 100' cement plug top of cut off.
  10. Pull tubing and spot 100' cement plug at shoe of 13-3/8" casing @ 346'.
  11. Pull tubing and remove 13-3/8" casing flange.
  12. Cap surface w/10 sks cement plug, install dry hole marker.
  13. Remove battery equipment, lines, cover pits and clean location.
- 100' plug @ top of 6" casing  
24 hr. notice

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By		
SIGNED	TITLE	DATE
Claude Aubert, Jr.	Area Superintendent	3-2-73
APPROVED BY	TITLE	DATE
Joe D. Ramey Dist. I, Supv.		
CONDITIONS OF APPROVAL, IF ANY:		