

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
FIELD STATE	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
GLADIOLA (Wolfcamp)	
12. County	
LEA	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator		
D. H. HUNT		
Address of Operator		
600 W. Illinois Suite #706 Midland, TX 79701		
Location of Well		
UNIT LETTER <u>A</u> , <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM		
THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>12S</u> RANGE <u>38E</u> NMFM.		

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. POOH WITH PUMP AND RODS
2. ND WELLHEAD. NU BOP.
3. PU ADDITONAL TUBING TO SPOT ACID (9600-9450). POOH WITH TUBING. (SLM)
4. PERFORATE WITH 4" CASING GUN 2 SPF. (FDC-CNL) 9600-14, 9584-90, 9560-70, 9492-96 (CORRELATE WITH CBL AND TIE-IN)
5. TIH WITH RBP AND PACKER. SET RBP AT 9690' AND TEST. DUMP TWO SXS SAND ON TOP OF PLUG. SET PACKER AT 9535'.
6. ACIDIZE PERFORATIONS AS PER DOWELL RECOMMENDATION.
7. FLOW AND/OR SWAB TO RECOVER LOAD. RE-ACIDIZE IF NECESSARY.
8. RELEASE PACKER AND RECOVER RBP.
9. MOVE PLUG TO 9530' AND TEST. DUMP TWO SXS SAND ON TOP OF PLUG. SET PACKER AT 9530'
10. ACIDIZE PERFORATIONS AS PER DOWELL'S RECOMMENDATION.
11. FLOW AND/OR SWAB TO RECOVER LOAD.
12. POOH WITH RBP AND PACKER.
13. TIH WITH ANCHOR AND TUBING.
14. ND BOP. NU WELLHEAD.
15. TIH WITH PUMP AND RODS.
16. MONITOR PRODUCTION.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Thomas Rogers TITLE District Superintendent DATE 8-22-88ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISORAPPROVED BY _____ TITLE _____ DATE AUG 29 '88

CONDITIONS OF APPROVAL, IF ANY: