

*TMBR "10" State No. 1
2630' FSL & 713' FWL
Sec. 10, T-14S, R-34E
Lea County, New Mexico*

PLUG & ABANDON PROCEDURE

1. Rig up completion unit. Unseat pump and POOH laying down rod string.
2. Nipple up BOP and POOH with 2 $\frac{7}{8}$ " tbg. Pick up 5 $\frac{1}{2}$ " CIBP and GIH w/tubing to $\pm 9950'$. Set CIBP and circulate hole w/9# 35 viscosity mud.
3. Spot ~~10~~ ²⁵ sx Cl "H" cement plug on top of CIBP @ 9950'. POOH with 2 $\frac{7}{8}$ " tbg.
4. Rig up wireline and freepoint 5 $\frac{1}{2}$ " casing. Cut 5 $\frac{1}{2}$ " casing at 6000' (est. recovery).
5. POOH and lay down 5 $\frac{1}{2}$ " casing. GIH with 2 $\frac{7}{8}$ " tubing to 6050' and spot 50 sx Cl "H" cement plug. Wait on cement 4 hrs and tag top of plug. @ 5950'
6. POOH with 2 $\frac{7}{8}$ " tubing to 4500' and spot 50 sx Cl "C" cement plug. Wait on cement 4 hrs and tag top of plug.
7. POOH with 2 $\frac{7}{8}$ " tubing to 2970' and spot 50 sx Cl "C" cement plug.
8. POOH with 2 $\frac{7}{8}$ " tubing to 535' and spot 50 sx Cl "C" cement plug. — TAG
9. POOH with 2 $\frac{7}{8}$ " tubing and set 15 sx Cl "C" cement plug at surface.

TMBR/Sharp



Drilling, Inc.

CURRENT WELLBORE

TMBR "10" STATE #1

2630' FSL & 713' FWL

SEC. 10, T-14S, R-34E

LEA CO., N.M.

RAN 11 JTS 13 3/8" CSG & SET
@ 481' CEMENT W/245 SX
CL "C" + 6% GEI + 2% CACI +
150 SX "C" + 2% CACI₂
CIRC. 42 SX

RAN 10 JTS 8 5/8" 32#
CSG & SET @ 4450'
CEMENT W/1470 SX ECONFILL
+ 15% GEI, + 1.88%_{SX} NACL
+ 200 SX "C" + 1% CACI₂.
CIRC. 131 SX

TOC-9020'

RAN 152 JTS 5 1/2" N-80 & 107 JTS
5 1/2" K-55 17# CSG. & SET @
11,245' CEMENT W/400 SX
CL "C".

TD-11,265'

PERFORATING RECORD

9-1-00: 10,850-10,860

9-20-00:

10,832-10,842

7-10-01:

10,020-10,028

8-29-01:

(10,019-27) (10,016-17)
(10,010-14)

SQUEEZE RECORD

10-4-00

10,832-10,842

7-7-01

CIBP SET @ 10,800 W/35 CEMENT

TMBR/Sharp



Drilling, Inc.

WELLBORE AFTER PLUGGING

TMBR 10 STATE #1
2630' FSL & 713' FWL
SEC. 10, T-14S, R-34E
LEA CO., NM

