

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Free ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPTH OF PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> WELL GAS <input checked="" type="checkbox"/> WELL OTHER-	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name Swearingen B
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 North 1980 FEET FROM THE LINE AND FEET FROM West 20 5-S 33-E TOWNSHIP RANGE NMPM.	10. Field and Pool, or Wildcat Und. Yeso
15. Elevation (Show whether DF, RT, GR, etc.) 4417' RDB	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:


PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon the subject well per the following:
Rig up service unit. Release Baker Model R packer set at 7629' and pull out of hole. RIH with CIBP and set at 7725' and cap with 35' of class C neat cement (5sx). Spot above plug 80 bbls of 10# brine with 25# gel/bbl. Run free point survey and cut the 5-1/2" casing 100' above the free point. Pull 5-1/2" casing. Spot in and out of the 5-1/2" casing stub 36 sx of class C neat cement. Spot above cement plug 100 bbls of 10# brine with 25# gel/bbl. Spot 45 sx of class C neat cement at 3000'. Spot above cement plug 80 bbls of 10# brine with 25# gel/bbl. Spot 55 sx of class C neat cement in and out of the 8-5/8" casing shoe (set at 1924'). Spot above the cement plug 115 bbls of 10# brine with 25# gel/bbl. Spot 10 sx of class C neat cement at surface. Cap well and erect permanent abandonment marker.

0+4-NMOCD,H 1-HOU, R.E.Ogden,Rm 21.150 1-F.J.Nash, HOU, Rm. 4.206 1-CMH

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Administrative Analyst	DATE 8-2-83
APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR	TITLE	DATE AUG 4 1983

CONDITIONS OF APPROVAL, IF ANY: