

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20716
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Miller 10
8. Well No. 1
9. Pool name or Wildcat Wildcat San Andres

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER ☐ Dry Hole in Plug-Back Zone	
2. Name of Operator Bledsoe Petro Corporation	
3. Address of Operator 3908 N. Peniel, Ste. 500, Bethany, OK 73008	
4. Well Location Unit Letter G : 1980 Feet From The North Line and 1650 Feet From The East Line Section 10 Township 6S Range 33E NMMPM Roosevelt County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4390 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subsequent Report of Plug Back Operations:

1. Set Cast Iron Bridge Plug @ 7750', Cap with 3 sx cement (35' fill up)
2. Perforate San Andres 4054'-4058' & 4068'-4074' with 2 shots per foot.
3. Swab test under packer. Set @ 4014', Swab well to seating nipple, Swab after 30 min. Recover 25' of fluid, 90% water, 9% BSW, 1% oil.
4. Treat San Andres perforations with 1500 gal. 20% NEFE acid.
5. Swab back load, check overnight fill up, all water with no show.

Notice of Intended Operations: SEE ATTACHED SHEET

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Thomas R. Conroy TITLE Lech. Engr. DATE 10/18/93
TYPE OR PRINT NAME Thomas R. Conroy TELEPHONE NO. (405) 789-5053

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

OCT 21 1993

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED

1P

ATTACHMENT TO FORM C-103

BLED SOE PETRO CORPORATION
MILLER 10-1
SEC. 10-6S-33E
ROOSEVELT COUNTY, NEW MEXICO

1. Fill hole with 9.3# mud.
2. Spot ²⁵10 sack cement plug (100') through tubing at 3300', check plug after 2 hours.
3. Cut off 4 1/2" casing at free point (est. 2500' - 3000')
4. Spot 25 sack cement plug (100 sacks) in 8 5/8" casing at top of 4 1/2" cut off. *500' / 500' cement*
5. Spot ¹⁰5 sack plug from 30 feet back to surface, cut off 8 5/8" 3' below ground level. weld on metal plate.
6. Back fill cellar, restore surface and install metal marker at wellhead.

EXISTING AFTER PE TO SAN ANDRES


Miller "10" Well No. 1

1980 FNL & 1650 FEL (Loc "B")

T65 - R33E, Roosevelt Co, NM

GL - 4390.2

KB - 4401.5



720 POSED Rugging

Miller "10" Well No. 1

1980 FNL & 1650 FEL (Loc "B")

TLS - R33E, Roosevelt Co, NM

GL - 4390.2

KB - 4401.5

