

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20722
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD	7. Lease Name or Unit Agreement Name Federal 9
2. Name of Operator Bledsoe Partners, Inc.	8. Well No. 1
3. Address of Operator 3908 N. Peniel, Suite 500, Bethany, OK 73008	9. Pool name or Wildcat Undesignated Silurian
4. Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>north</u> Line and <u>660</u> Feet From The <u>west</u> Line Section <u>9</u> Township <u>6S</u> Range <u>34E</u> NMPM <u>Roosevelt</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4367 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 7840' w/4 sx cement on top
2. Load hole with mud
3. Spot 100' plug in 5 1/2 csg @ 5840'.
4. Spot 100' plug in 5 1/2 csg @ 3840'.
5. Cut and pull 5 1/2 csg. from apx 2050'.
6. Spot 150' cement plug at cut off pt. 50' in stub (to get stub plug and surface pipe plug in one plug.)
7. Spot plug 30' to surface.
8. Cut and cap surf. csg., weld on dry hole marker, clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Vice President DATE 4/11/94  
TYPE OR PRINT NAME Gary J. Garbacz (405) 789-5053 TELEPHONE NO.

(This space for State Use)

**FOR RECORD ONLY**

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE APR 19 1994

CONDITIONS OF APPROVAL, IF ANY: