

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-79

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Eagle Oil & Gas Co.	8. Form or Lease Name Radcliff
3. Address of Operator 510 Hamilton Bldg., Wichita Falls, Texas 76301	9. Well No. 1
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>6S</u> RANGE <u>35E</u> N.M.P.M.	10. Field and Pool, or Wildcat Wildcat
11. Elevation (Show whether DF, RT, GR, etc.)	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/05/88 Set CIBP @ 7710' & cap with 20' cement. Circulate hole with 10# brine with 25# gel/bbl.
1/06/88 Cut off 4-1/2" casing @ 6500'. Casing parted. Pull out of hole with 77 joints, 3106'. Hit bridge @ 2215'.
1/07/88 Check with New Mexico Commission and received permission to spot 200' plug @ 3950'. Set 35 sx plug @ 3150-3050'.
1/08/88 Tag plug @ 2990'. Set 25 sx plug @ 2050-1950'. Tag plug @ 1925'. Spot 30 sx plug from 250-350'. Spot 10 sx surface plug from 13-3'. Cut 8-5/8" off 3' below ground level, weld on plate & install dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lena Shaffer (817) 723-7322 TITLE Engineering Assistant DATE 1/14/88

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE 1/14/88

CONDITIONS OF APPROVAL, IF ANY: