

PROCEDURE - CONTINUED

Page 2

NORTH ANDERSON RANCH UNIT WELL NO. 2-33
Anderson Ranch Wolfcamp Field
Lea County, New Mexico

10. P. U. to 4096' and spot 50 sxs Class "H" cmt PLUG NO. 4: 4196'-4096' (in and out of 8-5/8" csg).
11. POOH w/tubing.
12. Freepoint 8-5/8" csg and cut off @ approximately 2000'.
13. Lay down 8-5/8" casing.
14. Run in w/tubing O.E. and spot 45 sxs Class "H" PLUG NO. 5: across 8-5/8" stub.
15. P. U. to 642' and spot 55 sxs Class "H" PLUG NO. 6: 642'-542' (across 11-3/4" csg and shoe).
16. POOH w/tubing.
17. Spot PLUG NO. 7 10 sxs Class "H" cement 10'-surface.
18. Weld on $\frac{1}{2}$ " steel plate and leave dry hole maker.