

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions
reverse side)Form approved
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC 059576

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

Maljamar (Grayburg)

8. FARM OR LEASE NAME

Maljamar Unit

9. WELL NO.

58

10. FIELD AND POOL, OR WILDCAT

Maljamar
Grayburg-San Andres11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREASec., 10, T-17-S, R-32-E,
NMPM

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection Well

2. NAME OF OPERATOR

Chevron Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1660, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

Unit J, 1980' FSL, 1980' FEL, Section 10, T-17-S, R-32-E, NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR 4130

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU PU. Run over shot on tubing, latch onto fish @ 2641'. POOH w/tubing & packer.
2. Run and set CIBP on wireline to 3800'. Spot 35' cement on top of CIBP with dump bailer.
3. Load hole with mud laden fluid using tubing.
4. Determine free point of 5 1/2" casing (Est 2300'-70%)
5. Shoot off casing, pull and lay down 5 1/2" casing.
6. Run tubing, open ended, to 50' below casing stub and spot 50 sxs cement. Pull tubing to 343', Spot 50 sxs cement. Spot 10 sxs cement 20' to surface.
7. Cut casing 3' below ground level, weld steel plate with needle valve and marker. Back fill pit and clean up location.

APPROVED
RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED

J. E. Pullig
(This space for Federal or State office use)


TITLE Senior Drilling Engineer

DATE October 14, 1974

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE



*See Instructions on Reverse Side