

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Baish A
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit I	10. FIELD AND POOL, OR WILDCAT Malamar Abo
14. PERMIT NO. 30-025-00622	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 21-17S-32E
15. ELEVATIONS (Show whether DF, RT, CR, etc.)	12. COUNTY OR PARISH 13. STATE Lea NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOTING OR ACIDIZING

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and completion. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to the work.)

- ① Miru, set retainer @ 50' above fish (approx. 2980')
- ② Pump 500 sxs class "H" cmt & displace w/ 90 bbls wtr
- ③ Place cmt behind 7" csg as follows:
 - a. Perf w/ 4 JSPIF @ 2900'
 - b. Set retainer @ 2800'
 - c. Pump 500 sxs Class "H" cmt & pull out of retainer & spot 2-3 bbls cmt on top of retainer
- ④ Set cmt plug in 7" csg across top of salt by spotting 25 sxs class "H" cmt from 940' to 840'
- ⑤ Pull up to 50' from surface & spot 50' cmt plug at surface.
- ⑥ Cut off csg to final restored ground level and cover well w/ cmt cap that is 2' in diameter and 4" in thickness. Place abandonment marker in wellbore. A proposed P & A wellbore sketch is attached.
- ⑦ Verbal appl for this procedure given by Bob Pitcock on 3-3-86.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE 3-4-86

Original Filed 3-4-86

APPROVED BY

TITLE

DATE 3-21-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side