

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other instructions
verse side)

DATE

RECEIVED
Bureau No. 1001-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-029507B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MCA Unit

8. FARM OR LEASE NAME

MCA Unit Farm 3

9. WELL NO.

87

10. FIELD AND POOL, OR WILDCAT

Melamie SH

11. SEC. T. & M. OR BLK. AND
SURVEY OR AREA

22-17S-32E

12. COUNTY OR PARISH 13. STATE

Lea NM

1. OIL ☐ GAS ☐ OTHER ☒ Injection Well

2. NAME OF OPERATOR

Conoco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL & 1980' FWH - Unit Letter N

14. PERMIT NO.

30-025-00626

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETS

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Cement to Plug Hole

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Work started 10/6/88. MIPU. CO OH to 4154. Ran OH Caliper log & inj profile log. Spot "Puddle Pack" slurry over OH interval. DO Fundream. Repair 4 1/2' casing below WH. Ran 29 jts fiberglass liner over liner/hanger pks. Land shoe at 4143'. Cont with 140 x 50/80 prog. Set pks. Reverse out circulation, CO to TOC & test line, wet shoe. Squeezed shoe w/100 svcs. Dr cement 4107' - 4143'. Ran @ BL. Perf 3830' - 4110'. Acidize w/20 bbls 15% HCL & divert w/100# salt. Follow w/20 bbls HCL & 15% Block. Follow to 20 bbl HCL & 200# Block. Tail w/15 bbl HCL. Flow back. Run inspection equipment.

18. I hereby certify that the foregoing is true and correct

SIGNED

ADMINISTRATIVE SUPERVISOR

TITLE

DATE December 8, 1988

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 12-13-88

COPIES OF APPROVAL, IF ANY:

*See Instructions on Reverse Side