

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instruction
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. 63240 L C-058697(B)
2. NAME OF OPERATOR CONOCO INC.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	7. UNIT AGREEMENT NAME MCA
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit K	8. FARM OR LEASE NAME MCA Unit Bty 4
12. COUNTY OR PARISH Lea	9. WELL NO. 191
13. STATE NM	10. FIELD AND POOL, OR WILDCAT Malamar G/SA
14. PERMIT NO. 30-025-00693	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 25-17S-32E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 2615' FSL & 1345' FNL	12. COUNTY OR PARISH Lea

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☒

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- ① MIRU on 1/6/86. POOH w/ tbg & pump
- ② Tag @ 3813'. Collapsed csq from 3807'-3818'. Swaged out csq from 3807'-3818' w/ 5 1/4" swage and fell thru. Tag fill @ 4160', 12' of shot hole covered.
- ③ Dumped 5yds of pea gravel, Tag top of gravel @ 3778'. Clean out 8' bridge to 3786', then 2' bridge from 3808'-3810', and bridge from 3849'-3859'. Circ. hole clean. Top of pea gravel @ 3860'. Set pkr @ 3600' & press. test backside to 500 psi. Collapsed csq from 3807'-3818' hld @ 800 psi.
- ④ Drill out 50' of gravel to 3600'. Jet wash gravel from 3600'-3900'. Clean out to 4065'. Shot 4 sqz holes @ 100'. Set RBP @ 2400' & pkr @ 262'. Pumped 200 sxs class "H" cmt w/ 3% CaCl₂. Displaced cmt w/ 8 bbls fresh water. Got good returns to surface.
- ⑤ Drill out cmt & press. test backside to 500 psi for 30 min. POOH w/ RBP & set pkr @ 2340'. GIH w/ prod. equip. & rig down on 1/29/86.
- ⑥ Test pumped 14 BBL/23 BW on 2/6/86.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE 3-5-86

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL IF ANY

TITLE

DATE

MAR 12 1986

*See Instructions on Reverse Side