Form 3160-5 (June 1990)

1980' FSL & 1980' FWL

Sec. 26, T-17S, R-32E

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

unit &

LC 058408B 6. If Indian. Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Lea, NM

Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE MCA Unit Bty 4 1. Type of Well Oil Gas Well Well 8. Well Name and No. Injection Well 2. Name of Operator 9. API Well No. Conoco Inc. 3. Address and Telephone No. 300250070100 10. Field and Pool, or Exploratory Area 10 Desta Drive, Suite 100W, Midland, TX 79705 (915) 686-6548 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Maljamar Grayburg-SA 11. County or Parish. State

2.	REPORT, OR OTHER DATA			
	TYPE OF SUBMISSION	TYPE OF	TYPE OF ACTION	
	X Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection	
		Other	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to squeeze a shallow casing leak in this well and return it to injection as follows:

- 1. Pull out of hole with RBB at 1715'.
- Run bit and scraper to 3700'.
- Run in hole with RBP and packer to isolate casing leaks. A casing inspection log shows potentially bad casing between 1280'-1500' and 2300'-2350'.
- 4. Set retainer 100' above the leak and squeeze cement.
- 5. Drill out retainer and pressure test 7" casing.
- 6. Retrieve RBP and return to injection.

Signed Sales the foregoing is true and correct	Title _	Regulatory Coordinator	Date 3-27-91
(This space for Federal of State office use) Original State of State of Control of Cont			Date 4-9-9/
Approved by	Title _		Date