

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Item: No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC-057210

6. If Indian, Allotment or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. *Unit 2*

MCA Unit No. 207

9. API Well No.

30-025-00746

10. Field and Pool, or Exploratory Area

Mallam (G-SA)

11. County or Parish, State

Lea, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other: *Injection CO2*

2. Name of Operator

CONOCO INC.

3. Address and Telephone No.

10 DESTA DRIVE, STE 100 W, MIDLAND, TX 79705 (915) 686-5494

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FSL + 660 FEL

Unit letter P, Sect. 28, T17S, R32E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other: *Stimulate*

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-25-91 MURU. Pmp 6 BBLS Xylene. Flush w/CO2. Pmp 6 BBLS Xylene. Flush w/6.8 MCF CO2. Backflow 4 hrs. Return to inj. MURU. TFF at 4156 (CTD 4159). Pmpd 20 BBLS 10# brine down tbg. 2100# at start 1700# finish. RU to dump sand down tbg. Each time we tried to dump the sand it seemed to freeze up. AA + pmp 40 BBLS 10# brine. Dmp. 5 sks (500 lb) sand down tbg. Tag sand at 4082. Need sand at 4010. Tried to dump more sand but CO2 freezing up. Pmp 10# brine, dump 5 sks sand, acidize. Pmpd 20 BBLS 10# brine down tbg. Dropped 6 sks sand. Tagged sand at 3916 - circ out sand to 4008. Pmp 50 BBLS acid - circ sand out. Pmpd 50 BBLS 15% acid flushed w/12 BBLS 10# brine. Max press 1900#. With circ sand and acid out. RD. Put well on injection.

14. I hereby certify that the foregoing is true and correct

Signed

Christine L. Neff

Title ADMIN. ASSISTANT

Date

7-17-91

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: