Form 3160-5

## **UNITED STATES**

FORM APPROVED

(June 1990)	DEPARTMEN	T OF THE INTERIOR	Expires: March 31, 1993	
	BUREAU OF I	AND MANAGEMENT	5. Lease Designation and Serus No.	
SUNDRY NOTICES AND REPORTS ON WELLS			IC-059001	
Do not use t	this form for proposals to dri Use "APPLICATION FOR	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation	
I. Type of Well  Oil  Well  Well  Oil  Gas  Well  Well  Well  Well  Approved as to plugging of the well bore.  Liability ender bond is retained until				
			8. Well Name and No.	
2. Name of Operato			MCA232	
CONOCO INC.  3. Address and Telephone No.			30-025-0087 00807	
10 Desta Drive, ste 100 W. Midland, Texas 1-915-686-5424			10. Field and Pool, or Exploratory Area	
4. Location of Weil (Footage, Sec., T., R., M., or Survey Description)			Maljamar GB-SA	
Unit F 1880' from North line, 1980' from West line of			11. County or Parish, State	
Section 33, Township 17 S, and Range 32-E		Lea County, New Mexico		
12. CHI	ECK APPROPRIATE BOX(	s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA	
TYP	TYPE OF SURMISSION TYPE OF ACTION			
	Notice of Intent	Abandonment	Change of Plans	
57		Recompletion	New Construction	
Subsequent Report		Plugging Back	Non-Routine Fracturing	
Final Abandonment Notice		Casing Repair Altering Casing	XX Water Shut-Off Conversion to Injection	
		Other	Dispose Water	
			(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	
13. Describe Propose	ed or Completed Operations (Clearly state al	I pertinent details, and give pertinent dates, including estimated date of starting all depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled	
6/16/00	)− Gih w/4 1/2" cmt re	et: set cmt ret at 3500' stingout of	ret and cir 4 1/2"	
w/brine gel and test 4 1/2 casing to 500 psi. from 3500' to surface HELD!, sting into				
cmt ret and squeeze 25 sks of class c cmt under retainer at 1200 psi. spotted 10 sks of				
cmt on top of cmt ret. lay down tubing to 2550' and spot 25 sks plug class c cmt bottom				
of plug at 2550' and tag top of plug at 2188', 6/19/00 lay down tubing to 1460' and				
spot25 sks plug , bottom of plug at 1460' tag top of plug at 1040': cooh w/tubing and				
	Gih w/3 5/8" jet cutterand cut 4 1/2" casing off at 1000':6/20/00 started laying down			
		'00 perferated 7" casing at 2-shots950	· · · · · · · · · · · · · · · · · · ·	

(over) 14. I hereby certify that the foregoing is true and correct PETROLEUM ENGINEER JUL 1 2 2000 Approved by Conditions of approval, if any:

packer to get injection rate 2bbls per min. at 800 psi, got returns up 8 5/8" casing surface pipe. released packer and cooh w/packer and Gih w/7" cmt ret and set at 850' Mix 35 sks class c cement plug and pumped 35 sks under ret and spotted 10 sks cmt on top.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any artment or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Cooh w/tubing and setting tool and Gih w/wireline and perferated 2-shots at 300°, 6/21/00 GIH W/PACKER--set toolat 30' and pressure up to 1500 psi could not get an injection rate, Pumped down 8 5/8" surface pipe 800 psi no injection rate, Pumped down 7" casing under packer went to 1800 psi, pressure would bleed offgetting returns up 8 5/8" surface pipe but still could not get an injection rate, shut down and call blm--andy cortez, we decided to perferate at 250' w/4 shots, Gih w/ packerand got an injection rate of 2 bpm at 800 psi and got returns up 8 5/8" surface pipe. and also open hole 12 1/4" behind 8 5/8" surfacepipe. Mix 110 sks of class c cmt and pumped and got cmt returns up 8 5/8" surface pipe, and some cmt going in open hole behind 8 5/8" surface pipe. shut down and let cmt settle down in casing. 6/22/00 Mix cmt and pumped down 8 5/8" casing and filled up w/cmt to surface and fill inside 7" casing w/cmt approximate ly 50', finish fill open hole at surface and shut down, cut and remove wellhead and install dry hole marker and cut anchors and clean up location.

SHOEMED A CHES