

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW MEXICO 88240

SUBMIT IN TRIP DATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-059002

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection Well - Water

2. NAME OF OPERATOR
Conoco Inc.

3. ADDRESS OF OPERATOR
P.O. Box 460 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FWL & 660' FNL - Unit Letter D

14. PERMIT NO.

NA

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7. UNIT AGREEMENT NAME

MCA Unit

8. FARM OR LEASE NAME

MCA Unit Bty 3

9. WELL NO.

No. 224

10. FIELD AND POOL, OR WILDCAT

Maliama G-SA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

34-17S-32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. P00H w/ pks & Hg. Run csg scraper to 3905'. Get wash open
hole section from 3905'-4253'. Drill out cement 4253'-4286'. Circulate
hole clean. Run caliper log 3850' to TD. Pump 25 bbls 15% HCL-FC.
Reverse acid out w/ 64 bbls 8.4#/gal KCH water. Spot 26 bbls 15% HCL-
NE-FC mixed w/ 1 drum Checker-Sol from 4253'-3950'. Reverse circulate
wellbore clean w/ 81 bbls 8.4#/gal KCH water. Establish circulation
w/ 25 bbls 8.4#/gal KCH water. Spot 35 bbls resin slurry 4286'-3932'.
Flush w/ 19.3 bbls 8.4#/gal KCH water w/ 2% Clayfix. Wait on resin for
24 hrs. Tag top of resin, if need to drill out to 3926'. Tag top of
gravel between 3920'-3925'. Dump 1 sk Cal-Seal on gravel top. Set retainer
at 3800'. Pressure backside to 500 psi. Establish injection rate. Pump
20 sks class "C" w/ 2% CaCl₂ & 0.8% Halad-9. Follow w/ 30 sks
50/50 ppg. Flush w/ fresh water. Wait on cement 16-24 hrs.

18. I hereby certify that the foregoing is true and correct

SIGNED DE FINNEY

TITLE Administrative Supervisor

DATE September 22, 1987

(This space for General or State office use)

APPROVAL OF DE FINNEY
COMMISSIONER OF APPROVAL, IF ANY:

TITLE

DATE 9-28-87

*See instructions on Reverse Side

Subject to
Like Approval
by State

Title 18, N.M.S. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the
United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) - NMCO-Hobbs (3) Hondo (2) Cimarron (1) P. H. - P. H. (1)

MCA Unit No. 226

Page 2

Drill out retainer & cement from 3800'-3916'. Reverse circulate hole clean. Drill out Cal-Seal & pea gravel to 3926'. Drill out resin coated material to TD. Circulate hole clean & P.O.H. Run liner to 4186'. Run G.R.-CBH log from 4286'-3500'. Set liner hanger-pk. Cement liner w/58 sxs 50/50 poz class "C" w/0.75% Halad-4 modified. Flush w/20 bbls 8.34#/gal water. Reverse circulate hole clean w/9#/gal brine. Wait on cement 24 hrs. Scrape csq from surface to top of liner. Swab fluid level down to 1500' from surface. Log w/CBH-G.R. from 4286'-3500'. Perforate w/1 js pf from 4010'-4244' for total of 97 perfs. Run injection equipment & return to injection.