

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01221 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-2118
7. Lease Name or Unit Agreement Name State "G"
8. Well No. 9
9. Pool name or Wildcat Saunders Permian Penn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Charles B. Gillespie, Jr.	
3. Address of Operator P.O. Box 8 Midland, TX 79702	
4. Well Location Unit Letter A : 800 Feet From The North Line and 660 Feet From The East Line Section 4 Township 15-S Range 33-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4198' GR, 4211' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
1. Set 5 1/2" cast iron bridge plug above perforations at 9750' and cap with 35' cement.
 2. Load hole with mud.
 3. Cut off and pull 5 1/2" casing from approximately 6500'.
 4. Spot 100' cement plug at 5 1/2" casing stub with 50' in and 50' out and tag.
 5. Spot 100' cement plug across 8 5/8" shoe at 4185' and tag.
 6. Cut off and pull 8 5/8" casing from approximately 900'.
 7. Spot 100' cement plug at 8 5/8" casing stub with 50' in and 50' out and tag.
 8. Spot 100' cement plug across 13 3/8" shoe at 295'.
 9. 15 sx cement plug at surface.
 10. Weld 4" marker to surface pipe and clean location.

RECEIVED
MAR 18 1993
OIL CONSERVATION DIVISION
SANTA FE, NEW MEXICO

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William R. Crow TITLE Exploration Manager DATE 3/17/93

TYPE OR PRINT NAME William R. Crow TELEPHONE NO. (915) 683-1765

(This space for State Use)
ORIGINAL SIGNED BY JOHN SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAR 18 1993