

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-2118
7. Lease Name or Unit Agreement Name State 'G'
8. Well No. 10
9. Pool name or Wildcat Saunders Permo Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4210' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Charles B. Gillespie, Jr.
3. Address of Operator P. O. Box 8 Midland, Texas 79702	4. Well Location Unit Letter H : 2263 Feet From The North Line and 660 Feet From The East Line Section 4 Township 15-S Range 33-E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well currently has casing collapsed at 8455'. Proposal is to plug and abandon as follows:

1. Set cast iron bridge plug at 8400'. Dump 4 sx cement on top of bridge plug, WOC.
2. Set 25 sx plug at 7700' across top of ABO.
3. Cut off and pull 5 1/2" casing from approximately 6300'.
4. Set 25 sx plug across 5 1/2" casing stub.
5. Set 25 sx plug across 8 5/8" casing shoe at 4216'.
6. Cut off and pull 8 5/8" casing from approximately 1000'.
7. Set 50 sx plug across 8 5/8" casing stub.
8. Set 25 sx plug across 13 3/8" casing shoe at 296'.
9. Set 10 sx plug at top of surface casing.
10. Weld 4" marker to surface casing, and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David W. Hastings TITLE Production Manager DATE 7/18/89
TYPE OR PRINT NAME David W. Hastings TELEPHONE NO. 915-683-1765

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTIFIED 24 HOURS BEFORE THE PROPOSED PLUGGING OPERATION OR THE WELL TO BE ABANDONED.

JUL 20 1989