

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-01223 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-2118
7. Lease Name or Unit Agreement Name State G
8. Well No. 11
9. Pool name or Wildcat Saunders Permo Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4211' DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Charles B. Gillespie, Jr.
3. Address of Operator P.O. Box 8 Midland, TX 79702	4. Well Location Unit Letter B : 800 Feet From The North Line and 1980 Feet From The East Line Section 4 Township 15-S Range 33-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4211' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set cast iron bridge plug above perforations at 9700'.
Dump 4 sx cement on top of bridge plug.
- Cut off and pull 5 1/2" casing from approximately 6000'.
- Set 100' plug at 5 1/2" stub. 50' in and 50' out. Tag.
- Set 100' plug across 8 5/8" casing shoe at 4175'. — TAG
- Cut off and pull 8 5/8" casing from approximately 1700'.
- Set 100' plug at 8 5/8" casing stub. 50' in and 50' out. Tag.
- Set 100' plug across 13 3/8" casing shoe at 296'. — TAG
- Set 15sx plug at top of surface casing.
- Weld 4" marker to surface casing, and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kevin Widner

TITLE Production Manager

DATE 5/20/93

TYPE OR PRINT NAME

Kevin Widner

TELEPHONE NO. (915) 683-17

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

MAY 25 1993

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

THIS DOCUMENT MUST BE NOTED 24
HOURS AFTER THE DATE OF
ISSUANCE OF THE PERMIT
AND MUST BE NOTED 24 HOURS