DISTRIBUTION SANTA FE				Supersedes	~ 01d	
SANTAFE	 	NEW MEXICO OIL CONSERVATION COMMISSION			C-103	
	+ NEW	MEXICO OIL CONSERVA	TION COMMISSION	Effective	1-1-65	
FILE U.S.G.S.	+			5a. Indicate T	ype of Lease	
LAND OFFICE	+			State 👗	F'ee	
OPERATOR					Gas Lease No.	
					mmmm	
(DO NOT USE THIS FORM F	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)					
OIL GAS WELL WELL	OTHER-			7. Unit Agreer	nent Name	
Name of Operator CITIES SERVICE OIL COMPANY					3. Farm or Lease Name STATE AC	
P.O. BOX 69, Hobbs	s, N.M. 88240			9. Well No.	1	
Location of Well	660	North	660	Saunders	Pool, or Wildcat -Permo Penn	
Eas t	9	158	33E			
THE LINE,	SECTION	TOWNSHIP	RANGEN	MPM. ()		
	15. El	evation (Show whether DF, RT 4206 DF	GR, etc.)	12. County		
		7400 UF		1.00		
Ch		ox To Indicate Nature	=			
NOTICE	OF INTENTION TO	:	SUBSEQU	ENT REPORT O	F:	
PERFORM REMEDIAL WORK	F	PLUG AND ABANDON REME	DIAL WORK	A L	TERING CASING	
TEMPORARILY ABANDON			ENCE DRILLING OPNS.		IG AND ABANDONMENT	
PULL OR ALTER CASING	с	HANGE PLANS CASIN	G TEST AND CEMENT JOB		_	
		от	HER			
OTHER		U				
17. Describe Proposed or Comple	eted Operations (Clearly	state all pertinent details, an	d give pertinent dates, incli	ding estimated date	of starting any propose	
menner: 1. Could not load 2. Displaced 40 9 3. Still could not 7748 Ran co	d hole with much sack cement pluot load hole. ast iron bridge	ug loaded with L.C. Ran gauge ring on a plug on wire line	, material 10050 wire line. Shows and set at 7730	to 9780 . Med casing co	ollapsed at	
5. Shot 5½" casing Pulled 50243 (6. Displaced the (½ in and ½ or casing shoe), and installed	ng off at 6000° of $5\frac{1}{2}$ " casing. following came ut of $5\frac{1}{2}$ " casing (4" dry hole me	ent plugs through a ng stub), 30 sack p n.L 30 (in top	2 3/8" EUE tubing olug 4330-4230 (j of 8 5/8" casing	g: 30 sack p in and ½ ou p.) Reclaims	olug 5050-4950 it of 8 5/8"	
5. Shot 5½" casing Pulled 50243 (6. Displaced the (½ in and ½ or casing shoe), and installed 7. Cleared locat	ng off at 6000 of 5½" casing. following came ut of 5½" casing 10 sack plug (4" dry hole me ion of all mate	ant plugs through and stub), 30 sack plugs. i.L 30 (in top arker. erial and debris.	2 3/8" EUE tubing blug 4330-4230 (so of 8 5/8" casing Covered and level towards and belief.	g: 30 sack print and 1/2 ou g.) Reclaime	olug 5050-4950 it of 8 5/8" ad well head	
5. Shot 5½" casing Pulled 50243 (6. Displaced the (½ in and ½ or casing shoe), and installed 7. Cleared locat	ng off at 6000 of 5½" casing. following came ut of 5½" casing 10 sack plug (4" dry hole mate ion of all mate	ent plugs through and sack plugs stub), 30 sack plugs through and the sack plugs through a sack plugs thr	2 3/8" EUE tubing blug 4330-4230 (so of 8 5/8" casing Covered and level towledge and belief.	g: 30 sack print and 1 out.).) Reclaiment and pits.	olug 5050-4950 it of 8 5/8" od well head	

FELLEVED

11 1 1971

OIL CONSERCATION COMM. HOURS, N. M.